

**RECEIVED**Form 3160-5  
(September 2001)

APR 07 2009

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED  
OMB No 1004-0135  
Expires January 31, 2004**HOBBSOCD**  
**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an**  
**abandoned well. Use Form 3160-3 (APD) for such proposals.****SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. I-1, I-1, I-1

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Herman L. Loeb

3a. Address

P O Box 524, Lawrenceville, IL 62439

3b. Phone No. (include area code)

(618) 943-2227

4. Location of Well (Footage, Sec., T. R., M. or Survey Description)

1980' FNL 660' FWL Section 34-23S-R36E

5. Lease Serial No.

NMLC-030556A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Stevens A-34 #1

9. API Well No.

30-025-09459

10. Field and Pool, or Exploratory Area

Jalmat (Tansil, Yates, Seven Rivers)

11. County or Parish, State

Lea County, NM

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

*Well SI 1/88. No Justification For TA. Plug or Produce within 90 days. Denied f. Amos 3/31/09*

We will have a well service rig on this well to test it within the next month. We will make a decision to either produce the well or plug it and file another notice based on that decision.

BLM Bond # NM-2839

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

G. A. Payne

Title Petroleum Engineer

Signature

Date 3/20/09

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

DISTRICT 1 SUPERVISOR

Date

APR 08 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within the jurisdiction of such department or agency.

(Instructions on reverse)