Submit 3 Copies To Appropriate District Office District I	State of New Mexico		
District I 1625 N. French Dr, Hobbs, NM 88240 ECEIVED District II 1301 W. Grand Ave., Artesia, NM 8821APR 0 9 2004220 South St. Francis Dr. 1000 Rio Brazos Rd, Aztec, NM 87440BBSOCD Santa Fe, NM 87505 District IV 1200 St. Francis Dr. Santa Fe, NM 87505		June 19, 2008 WELL API NO. 3000501190	
		5. Indicate Type of Lease STATE FEE X	
District IV BUDDUU 1220 S. St. Francis Dr , Santa Fe, NM 87505	PAGE 1 OF 1	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name SOUTH CAPROCK QUEEN UNIT	
1. Type of Well: X Oil Well Gas Well 🗌 Other 📈		8. Well Number	
2. Name of Operator KEVIN O BUTLER & ASSOCIATES, INC.		9. OGRID Number / 12627	
3. Address of Operator PO BOX 1171, MIDLAND, TEXAS 79702	10. Pool name or Wildcat 8559 CAPROCK QUEEN		
4. Well Location			
Unit Letter C 330 feet from th Section 33 Township 14	S Range 31E NMPM	CHAVES County	
11. Elevatio 4277.80'	on (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate	Box to Indicate Nature of Notice,	Report or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.	P AND A
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB	`
DOWNHOLE COMMINGLE				

OTHER: RETURN WELL TO PRODUCTION

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

OTHER:

- Rig up well service equipment, investigate unknown artificial lift failures, repair and return to production.
- Currently doing road repair in order to access with rig and other needed equipment.
- Wells is down steep hill located below the Caprock.
- Investigating the possibility of access to well on the south end by a different road that will not be using the hill.
- Roads going down the hills are in very bad shape.
- Rigging up on the well in the next 2-4 weeks.

Spud Date: Rig Release Date:
I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE
Type or print name KEVIN O BUTLER E-mail address: robie@geedmidland.com PHONE: 432-682-1178For State Use Only
APPROVED BY: