Submit 3 Copies To Appropriate District Office Stat	e of New Mexico	Form C-103
Protect I Energy Mine	erals and Natural Resources	June 19, 2008
1625 N French Dr., Hobbs, NM		WELL API NO. 3002529066
OIL-CONS	ERVATION DIVISION	5. Indicate Type of Lease
District III APR 0 9 7(1)03 1220 S	South St. Francis Dr.	STATE X FEE \(\square\)
DISTRICT IV	1 0, 1 1111 0 7 5 0 5	6. State Oil & Gas Lease No.
87505	PAGE 1 OF 1	
SUNDRY NOTICES AND REPORT (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" PROPOSALS.)	DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit-Agreement Name STATE LAND 76
1. Type of Well: X Oil Well Gas Well Othe	er V	8. Well Number / 003
2. Name of Operator KEVIN O BUTLER & ASSOCIATES, INC.		9. OGRID Number 12627
3. Address of Operator		10. Pool name or Wildcat
PO BOX 1171, MIDLAND, TEXAS 79702		1900 ANDERSON RANCH WC
4. Well Location		
	SOUTH line and	
Section 2 Townsh	1	NMPM LEA County
11. Elevation (She 4301.9' GR	ow whether DR, RKB, RT, GR, etc.)	
4501.7 GR		
12. Check Appropriate Box	to Indicate Nature of Notice,	Report or Other Data
•••	1	•
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABAN		SEQUENT REPORT OF:
TEMPORARILY ABANDON X CHANGE PLANS		
PULL OR ALTER CASING MULTIPLE COMF		_
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
OTHER: 13. Describe proposed or completed operations. (C	OTHER:	give pertinent dates, including estimated date
13. Describe proposed or completed operations. (C of starting any proposed work). SEE RULE 11	Clearly state all pertinent details, and	
13. Describe proposed or completed operations. (C	Clearly state all pertinent details, and	tach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (C of starting any proposed work). SEE RULE 11	Clearly state all pertinent details, and 03. For Multiple Completions: At	each wellbore diagram of proposed completion
13. Describe proposed or completed operations. (C of starting any proposed work). SEE RULE 11	Clearly state all pertinent details, and 03. For Multiple Completions: At	each wellbore diagram of proposed completion
13. Describe proposed or completed operations. (C of starting any proposed work). SEE RULE 11	Clearly state all pertinent details, and 03. For Multiple Completions: At	each wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Conformal of starting any proposed work). SEE RULE 11 or recompletion.	Clearly state all pertinent details, and 03. For Multiple Completions: At	each wellbore diagram of proposed completion
 Describe proposed or completed operations. (Consistential of starting any proposed work). SEE RULE 11 or recompletion. Well Status - Request Temporary Abando 2) Effective - 4/09 Reason - Unable to operate in the current 	Clearly state all pertinent details, and 03. For Multiple Completions: At	each wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Conference of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into proposed work).	Clearly state all pertinent details, and 03. For Multiple Completions: At	each wellbore diagram of proposed completion
 Describe proposed or completed operations. (Consistential of starting any proposed work). SEE RULE 11 or recompletion. Well Status - Request Temporary Abando 2) Effective - 4/09 Reason - Unable to operate in the current 	Clearly state all pertinent details, and 03. For Multiple Completions: Attorners condition condition Condition Condition of	tach wellbore diagram of proposed completion 10 MIT 10 2009 4-10-2009 Approval: Notify OCD Hobbs
13. Describe proposed or completed operations. (Conference of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into proposed work).	Clearly state all pertinent details, and 03. For Multiple Completions: Attorners condition condition Condition Condition of	tach wellbore diagram of proposed completion No MIT 4-10-2009
13. Describe proposed or completed operations. (Conference of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into proposed work).	Clearly state all pertinent details, and 03. For Multiple Completions: Attorners condition condition Condition Condition of	tach wellbore diagram of proposed completion 10 MIT 10 2009 4-10-2009 Approval: Notify OCD Hobbs
13. Describe proposed or completed operations. (Conference of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into proposed work).	Clearly state all pertinent details, and 03. For Multiple Completions: Attorners condition condition Condition Condition of	tach wellbore diagram of proposed completion 10 MIT 10 2009 4-10-2009 Approval: Notify OCD Hobbs
 Describe proposed or completed operations. (Consistential of starting any proposed work). SEE RULE 11 or recompletion. Well Status - Request Temporary Abando 2) Effective - 4/09 Reason - Unable to operate in the current 4) Future Plans - Rework and bring into prospect of Future Plans - 2009 	condition	tach wellbore diagram of proposed completion 10 MIT 10 2009 4-10-2009 Approval: Notify OCD Hobbs
13. Describe proposed or completed operations. (Conference of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into proposed work).	Clearly state all pertinent details, and 03. For Multiple Completions: Attorners condition condition Condition Condition of	tach wellbore diagram of proposed completion 10 MIT 10 2009 4-10-2009 Approval: Notify OCD Hobbs
 Describe proposed or completed operations. (Consistential of starting any proposed work). SEE RULE 11 or recompletion. Well Status - Request Temporary Abando 2) Effective - 4/09 Reason - Unable to operate in the current 4) Future Plans - Rework and bring into prospect of Future Plans - 2009 	condition	tach wellbore diagram of proposed completion 10 MIT 10 2009 4-10-2009 Approval: Notify OCD Hobbs
 Describe proposed or completed operations. (Consistential of starting any proposed work). SEE RULE 11 or recompletion. Well Status - Request Temporary Abando 2) Effective - 4/09 Reason - Unable to operate in the current 4) Future Plans - Rework and bring into prospect of Future Plans - 2009 	condition Condition Condition Confice 24 ho	Approval: Notify OCD Hobbs ours prior to running MIT Test & Chart
 13. Describe proposed or completed operations. (Conformal of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective – 4/09 3) Reason - Unable to operate in the current 4) Future Plans – Rework and bring into prospect of Future Plans – 2009 Spud Date: 	condition Condition Condition Confice 24 ho	Approval: Notify OCD Hobbs ours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Constarting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective – 4/09 3) Reason - Unable to operate in the current 4) Future Plans – Rework and bring into prospect of Future Plans – 2009 Spud Date:	condition Office 24 ho	Approval: Notify OCD Hobbs ours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Constarting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into prospect of Future Plans - 2009 Spud Date:	condition Condition Condition Confice 24 ho	Approval: Notify OCD Hobbs ours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Conference of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into prospect of Future Plans - 2009 Spud Date: I hereby certify that the information above is true and considerable or print name KEVIN O BUTLER E-mail address.	Clearly state all pertinent details, and 03. For Multiple Completions: Attended to the condition of the cond	Approval: Notify OCD Hobbs ours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Conference of starting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into prospect of Future Plans - 2009 Spud Date: I hereby certify that the information above is true and considerable of Future Plans - 2009	Condition Condit	Approval: Notify OCD Hobbs ours prior to running MIT Test & Chart TE 4-7-09 HONE: 432-682-1178
13. Describe proposed or completed operations. (Confistarting any proposed work). SEE RULE 11 or recompletion. 1) Well Status - Request Temporary Abando 2) Effective - 4/09 3) Reason - Unable to operate in the current 4) Future Plans - Rework and bring into prospect of Future Plans - 2009 Spud Date: I hereby certify that the information above is true and considerable structure. SIGNATURE Type or print name KEVIN O BUTLER E-mail address for State Use Only	Clearly state all pertinent details, and 03. For Multiple Completions: Attended to the condition of the cond	Approval: Notify OCD Hobbs ours prior to running MIT Test & Chart TE 4-7-09 HONE: 432-682-1178