Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I 1625 N. French Dr., Hobbs, NM 88240 WELL API NO. District II 30-025-23796 OIL CONSERVATION DIVISION 1301 W. Grand Avenue, Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 STATE Z **FEE** Santa Fe, NM 87505 **District IV** State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 B-1732 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Harry Leonard (NCT-C) Oil Well Gas Well Other Name of Operator 8. Well No. Chevron USA Inc. 12 **Address of Operator** 9. Pool name or Wildcat 15 Smith Rd, Midland, TX, 79705 Drinkard **Well Location** 660 North Unit Letter feet from the 410 line and East feet from the 36 Section Township 21-S Range 36-E Lea **NMPM** County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON **REMEDIAL WORK ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. **PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE** CASING TEST AND COMPLETION **CEMENT JOB** OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag 7" CIBP at 6267, spot 25sx, plug 6267-6100 (Drinkard) WOC Tag. 3. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL. 4. Spot 40sx, plug 6050-5800 (7" Shoe, Lnr Top) WOC Tag. 5. Spot 35sx, plug 3400-3200 (Queen). TIEC 2003 6. Spot 35sx, plug 2600-2400 (B-Salt, Yates) WOC Tag. 7. Perf 4 holes at 1280, sqz 70sx, plug 1280-1100 (9 5/8 Shoe, T-Salt) WOC Tag. 8. Perf 4 holes at 250, sqz 85sx, plug 250-Surf 7" x 9 5/8" csgs (Surf) WOC Tag. Hobbs 9. Install dry hole marker. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BUILDING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** DATE 12/6/2003 TITLE **HES Specialist** Type or print name G.R. Bledsoe Telephone No. (432) 687-7153 (This space for State use) OC DISTRICT SUPERVISOR/GENERAL MANAGER no Eselian TITLE APPPROVED BY **DATE 1 2 7003**

Conditions of approval, if any:

