	Submit 3 Copies To Appropriate District Office	State of New Me	exico	Form C-103	
	office istrict I 625 N. French Dr., Hobbs, NM 882 DECEMPENT Minerals and Natural Resources		ıral Resources	June 19, 2008 WELL API NO.	
	1625 N. French Dr., Hobbs, NM 88240 OF THE STREET OF THE S			30-025-33678	
			DIVISION	5. Indicate Type of Lease	
			ncis Dr.	STATE FEE	
			7505	6. State Oil & Gas Lease No.	
	1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS			2261	
				7. Lease Name or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			. /	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			North Feather State Unit	
	PROPOSALS.) 1. Type of Well: Oil Well Gas Well	Other 🗸	/	8. Well Number 2	
	2 Name of Operator	Name of Operator		9. OGRID Number 213179 /	
	HILBROWN Operating, L.L.C.		10. Pool name or Wildcat Feather Marro		
	3. Address of Operator P.O. Box 223	37		Not Anderson Ranch Wolframp North	
	Midland, To	2 79702		NTADAUSON ROBER WOLLAND 100	
	4. Well Location				
	Unit Letter I: 1340 feet from the 500th line and 990 feet from the east line				
	Section 9	Township 15-5 R		NMPM County Lea V	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.			المنتان المستراج المنتاب المستخد المنتاب الموثر المنتاب المنتا	
	4301' Grd				
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	NOTICE OF INTENTION TO: SU			SEQUENT REPORT OF:	
	PERFORM REMEDIAL WORK PLUG	AND ABANDON 💢	REMEDIAL WOR	K ☐ ALTERING CASING ☐	
	TEMPORARILY ABANDON 📋 CHANG	SE PLANS	COMMENCE DR	ILLING OPNS. P AND A	
,		PLE COMPL	CASING/CEMEN	T JOB []	
	DOWNHOLE COMMINGLE				
	OTHER:	П	OTHER:	П	
		rations. (Clearly state all		d give pertinent dates, including estimated date	
	of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
	or recompletion.				
	Casing record: 1336"4	816@ 535'- cm	tcircid	TDe 12,506'	
DTS	DISPLACE WELL W/MLF 85/8" 32 16 @ 4050'- ONLY COTCH PBTD@ 11,665'				
951	DISPLACE WELL W/MLF 85/8" 32 16 @ 4050'- cont circ'd PBTD@ 11,665' 9.5 BRINE W/12.5# 9EL 51/2" 17.2016@ 12500'- cont circ'd Perfs 9769-9844'				
PER BBL.					
1. Set (IBP @ 9700' w/ 35' cmt on top. (A.) 100' 0225 =x5 @ 6700'					
	2. 100'(70sks) access	05. 4.6.	1 (IA.) 10	0 0 2 3 3 4 5 0 10 10 10 10 15 10 15 10 15 10 15 10 15 10 15 15 10	
2. 100' or (705) across 858" shoe @ 4050' 4100' woc \$ TAG (2A) 100' or 255x4@ 156					
	3. 100'or (20 sks) across 1338 shoe @ 585' WOLFTAG				
	4, 60' plug e surface	دم_		conservation Division Must be notified	
* 1	• 6.3		24 6	prior to the beginning of plugging operations.	
4. /	ALL CMT PLUGS 100' OR 25 5x	G WHICHEVER I	, وا نسم		
	Spud Date:	Rig Release D	ate:		
	Spud Date.	Kig Kelease D	ас.		
	I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
	t makes y seems and another account as a seempters to also control any and makes and control.				
	SIGNATURE Carton Whele TITLE Operations Manager DATE 4-15-09				
	For State Use Only	E-mail addres	s:	PHONE: 432 683 5216	
	APPROVED BY: Maley Librown TITLE Compliance Officer DATE 4/23/2009 Conditions of Approval (if any)				
	APPROVED BY: / Valey Librar	UN TITLE CON	notiones (Steen DATE 4/23/2009	
	Conditions of Approval (if any)		1	00	
	V				