Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural 1	
District I 1625 N French Dr., Hobbs, NM 87244 District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410APR 2 / 2009 Santa Fe, NM 8750	IVISION WELL API NO. 30-025-39221 S Dr. 5. Indicate Type of Lease
District IV 1220 S. St. Francis Dr., Santa Fe, NMHOBBSOCD 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR P DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	LUG BACK TO A DR SUCH 7. Lease Name or Unit Agreement Name: Bridges State
1. Type of Well: Oil Well Gas Well X Other	8. Well Number /
2. Name of Operator XTO Energy, Inc.	9. OGRID Number 005380
 Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701 Well Location 	10. Pool name or Wildcat Vacuum; Atoka-Morrow, North (Gas)
Unit Letter P: 760' feet from the South line and 660' feet from the East line	
Section 15 Township 17S Range 34E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11.	
11. Elevation (Snow whether DR, KKD, K1, GK, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE Image: Complement of the second se	
	HER: Complete & RWTP
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
3/01/09 MIRU PU. ND WH & NU 10K BOP. 3/03/09 PU RIH w/4-5/8" bit, 6-3-1/2" DC's & 266 jts of 2-7/8" 6.5#, L80 mew tbg. Tag DV tool @ 8,884'.	
RU swivel & DO DV tool. CO & RD swivel. 3/04/09 RIH w.ttl of 371 jts of 2-7/8" 6.5#, L80 new tbg. Tag @ 12,306'. (PBTD 12,318"). Circ w/360 bbls	
of 7% kcl wtr. POOH w/2-7/8" L80 tbg & LD BHA. Pmpd 31 bbls of 7% kcl wtr dwn csg. 3/05/09 RU WL trk. RIH w/Radial Bond Log/Gamma Ray/CNL logging tools. Tag @ 12,284'. Correlate depth to Halliburton Dual Spaced Neutron Spectral Density Log. Log fr PBTD to 11,500'. Then log from PBTD to 4600' & turn off CNL. Continue to run Radial Bond Log/Gamma Ray to surface. RD. Continued.	
Spud Date: 11/23/08 Rig Release I	Date: 12/31/08
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE March Ward TITLE	Regulatory Analyst DATE 04/17/09
kristy_ward@xtoenergy.com Type or print name Kristy Ward E-mail address:	
For State Use Only APPROVED BY	DATE DATE
Conditions of Approval (if any):	

- 3/6/2009 RIH w/2-7/8" SN & 154 jts of 2-7/8" L80 tbg to 5,035'. POOH w/2-7/8" L80 tbg. ND 10K BOP & NU Wood Group frac valve. RU WL. RU STS Services 10k lubricator. RIH w/3-3/8" Millennium csg guns & correlated w/Halliburton log. Perf Morrow interval fr 12,182'-12,187' (5', 10 holes) 12,194'-12,202'(8', 16 holes) 12,207'-12,215' (8', 16 holes) w/2 SPF. POOH, RD STS 10K lubricator WL equipment.
- 3/10/2009 MRU Frac equipment. Frac Morrow perfs from 12,182'-12,187', 12,194'-12,202' & 12,207-12,215' w/2,000 gals 7-1/2% Clay-Safe acid ahead of 60,000 gals 65 Q Foam & 60,000# 20/40 Sintered Bauxite sd dwn 5-1/2" 17# csg. Flush w/282 bbls 35# Water Frac CMHPG. RD pmp equip.
- 3/11/2009 Pro Well flwg back on a 12/64" choke. CO2 level is 20% w/light frac sd. Attempted to gauge tank to must ice in tank.
- 3/12/2009 SWI for 5 hrs due to blow dwn line & tank frozen. Attempted to gauge tank to must ice in tank. Rec 84 bbls of condensate. Rec 66 bbls of oil.
- 3/17/2009 RU WL trk & 5K lubricator. RIH w/4.70" OD gauge ring, WL & tag DV tool
 @ 8,884'. POOH w/WL & LD 4,70" OD gauge ring. RIH w/4.650" OD gauge ring, WL & tag DV tool @ 8,884'. POOH w/WL & LD 4.650" gauge ring. RIH w/4.625" OD gauge ring, WL & tag @ 12,182'. (top perf @ 12,182'). POOH w/WL & LD 4.625" OD gauge ring. RIH w/2.875" Mill shoe collar, 2.313" XN landing nipple, 2-7/8" x 2' L-80 tbg sub, 5-1/2" 17# PLT-V2 pkr, 2.313" x profile nipple top & WL. Correlated depth w/Halliburton log & set pkr @ 12,100'. POOH w/WL & setting tool. RD equip.
- *3/18/2009* RU pmp trk. BWDTT thru choke while pmpg 50 bbls of 7% KCL wtr dwn csg. Attempted to BWDTT for 2.5 hrs. (when press dropped to 40 psig open 2" valve on manifold & csg valve). RD equip.
- 3/19/2009 BWDTT thru choke. RU pmp trk & pmpd 85 bbls of 7% KCL wtr dwn csg, on the last 15 bbls had to pmpd @ 3.0 BPM to put well on vac, while ND Wood group frac valve & NU 10K BOP. RU vac trk. RIH w/Halliburton on/off tool & 290 jts of 2-7/8" L80 prod tbg. Well started gasing up tbg. SWI w/100 psig on tbg & light blow on csg. Pmpd 10 bbls of 7% KCL wtr dwn tbg. (vac). Opened csg valve after 15 min w/150 psig, in 20 min FCP-600 psig. Pmpd 20 bbls of 7% KCL wtr dwn csg. (vac). Pmpd 5 bbls of 7 % KCL wtr dwn tbg. (vac). Opened csg valve after 30 min w/150 psig. RD Lobo & Maclaskey equip.
- 3/20/2009 BWDTT thru choke. RU Lobo pmp trk, pmpd 80 bbls of 7% KCL wtr dwn csg & 30 bbls of 7% KCL wtr dwn tbg. Continue RIH w/ttl of 371 jts of 2-7/8" L80 prod tbg. Latched onto pkr & ND BOP. NU Wood Group new WH. RD Lobo equip.

3/21/2009 RDMO Key PU.

Bridges State #516 Completion & RWTP Page 2

- 3/24/2009 RU Pro WL trk. RIH w/FT & WL. Latched onto plug @ 12,098'. POOH w/WL & plug. RD Pro WL equip. RWTP.
- 3/25/2009 Post WO well test: 13 BO, 0 BW & 338 MCF in 24 hrs.
- 3/29/2009 Post WO well test: 25 BO, 0 BW & 408 MCF in 24 hrs.
- 4/09/2009 Post WO well test: 43 BO, 0 BW & 919 MCF in 24 hrs.
- 4/17/2009 Post WO well test: 40 BO, 1 BW & 987 MCF in 24 hrs.