Submit One Copy To Appropriate District Office District I 1635 N. French Dr. Hobbe NM 88340	Form C-103
District I Energy, Minerals and Natural Resources	March 18, 2009
1625 N. French Dr., Hobbs, NM 88240 District II APR 2 2 2009 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	WELL API NO. 30-025-22213
District III HOBBSOCD 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NW Defit	STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Jal Water System
1. Type of Well: Oil Well Gas Well X Other Water Well	8. Well Number #1
2. Name of Operator / Chevron USA	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
PO Box 7139, Midland, Texas 79708	WSW: Capitan-
4. Well Location	wsw, (aprair
4. Well Location Unit Letter M: 1313 feet from the South line and 1309.7 feet from the West line	
Section 16 Township 24S Range 36E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3380" Est.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB	
OTHER:  X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME I FACE NAME WELL NUMBER ADJANTABLE OUT DEED TO A CONTROL OF THE	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY	
STAMPED ON THE MARKER'S SURFACE.	
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other	
production equipment.	
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from	
lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to	
be removed.)	
X All other environmental concerns have been addressed as per OCD rules.	
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved	
now lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE	
For State Use Only	PHONE:
The same say only	. 1
APPROVED BY: Washington TITLE Comp. Office Conditions of Approval (if any):	cer DATE 04/28/2009