New Marico Off Conservation Division, District

1625 N. French Drive

Form 3160-5 (February 2005)

(Instructions on page 2)

UNITED STATES , NM 88240 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No. NM 23018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name

Do not use this f abandoned well.	orm for proposals to drill or to Use Form 3160-3 (APD) for su	o re-enter an ch proposals.	
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.
1. Type of Well Other Other			8. Well Name and No. Federal "J" No.1
2. Name of Operator H. L. Brown Operating, L.L.C.			9. API Well No. 30-041-20505
3a. Address 300 W. Louisiana Midland, TX 79702	3b. Phone No (432) 683	. (include area code) 3-5216	10. Field and Pool or Exploratory Area Bluitt San Andres (gas)
4. Location of Well (Footage, Sec., T., 1650' FN & EL Sec 10 T-8-S, R-37-E	R.,M., or Survey Description)		11. Country or Parish, State Roosevelt, NM
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA			
TYPE OF SUBMISSION TYPE OF ACT		NOI	
Notice of Intent		ture Treat Reci	water Shut-Off amation Well Integrity Other
Subsequent Report Final Abandonment Notice	Change Plans Plug	and Abandon Tem	porarily Abandon er Disposal
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 4-16-09: MIRU PU, NU BOP; perfed San Andres 4507-40' (4spf). 4-17-09: TIH w/ tbg and pkr, set @ 4401'; swb'd back load wtr. SD for holiday weekend. 4-20-09: Acidized w/ 2000gals 15% NEFE; started swb'g back load wtr. MAY 0 5 2009 4-23-09: Released pkr and TOH; TBIH w/ BHA, TAC and tbg to set SN @ 4555'. ND BOP. 4-24-09: TIH w/ pump and rods, hang well and RD PU. Start pumping back load wtr; made 32 BLW overnight 4-25-09: Pumped 7 BLW up tbg; flowed 100 MCF up csg to sales.			
14. I hereby certify that the foregoing is true and correct. Name (PrintedTyped) Carlton Wheeler Signature CarHon Wheeler		Title Opoerations Manager Date 04/27/2009	
ACCEPTED FOR RECEIVES SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by /S/DAVII Conditions of approval. MAY are attache	DR. GLASS 2000 proval of this notice does not warrant or little to those rights in the subject lease which w	Trit PETROLEUM	nns\/ 0000
entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1900 and Title 33 U.S.S. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any fall fictitious or fraudulent statements of representations as to any matter within its jurisdiction.			