

Submit 3 Copies To Appropriate District Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88201
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
20 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAY 04 2009

HOBBS

WELL API NO. 30-025-36464 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. BO-1581-0012
7. Lease Name or Unit Agreement Name Shelley 36 State ✓
8. Well Number 6
9. OGRID Number 151323 ✓
10. Pool name or Wildcat Skaggs Abo North
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,600' GR

SUNDRY NOTES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Pride Energy Company

3. Address of Operator
P O Box 701950, Tulsa, OK 74170-1950

4. Well Location

Unit Letter N : 1980 feet from the West line and 660 feet from the South line
Section 36 Township 19S Range 37E NMPM Lea County ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Propose to:

- Set cast iron bridge plug in 4" liner with wireline at 7,100', and dump ^{35'} 2 sacks of cement on top of CIBP.
- Set cast iron bridge plug in 4" liner with wireline at 6,800', and dump ^{35'} 2 sacks of cement on top of CIBP.
- Perform Mechanical Integrity Test and temporarily abandon the well. ^{35'}

Conditions of Approval: the operator shall give 24 hour notice the the appropriate District office before work begins.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mathew L. Pride BY: Pride Production Co., Inc. TITLE: General Partner DATE: 4/27/2009

Type or print name Mathew L. Pride, President E-mail address: mattp@pride-energy.com PHONE: 918-524-9200

For State Use Only

APPROVED BY: Cam M. Hill TITLE DISTRICT 1 SUPERVISOR DATE MAY 14 2009
Conditions of Approval (if any):