Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-HODES	FORM APPROVED OMB NO 1004-0135 Expires: November 30, 2000				
Lease Serial No.					


SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

	FORM AFFROYED	
	OMB NO 1004-0135	
OCD-HORE	Expires November 30, 2000	
CENE	Lease Serial No.	
MAY 1 0 200	NM-62667 6 If Indian, Allottee or Tribe Name	
11M1 1 2 200	6 If Indian, Allottee or Tribe Name	
HOBBSOCI		
	·	

abandoned well. Use For	m 3160-3 (APD) for	such proposals.	DBBSOC		
SUBMIT IN TRIPLICATE -	Other instructions			7. If Unit or CA/Agreement, Name and/or N	
1 Type of Well Oil Well X Gas Well Other 2. Name of Operator Occidental Permian Limited Partners	thin /	15798	84	8. Well Name and No. Gillully B Federal #6Y/ RA A	
3a. Address P.O. Box 50250, Midland, TX 79710- 4. Location of Well (Footage, Sec., T., R., M., or Survey) 390 FNL 660 FEL NENE(A) Sec 21 T2	0250 Description)	3b. Phone No. (<i>include are</i> 432 - 685 - 5717		9. API Well No. 30-025-06201 10 Field and Pool, or Exploratory Area Eumont Yates-SR-Qn	
12. CHECK APPROPRIATE	BOY(ES) TO IND	NCATE NATURE OF	NOTICE REP	Lea NM	
TYPE OF SUBMISSION	BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION				
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production Reclamation Recomplete		
Final Abandonment Notice	Change Plans Convert to Injection	X Plug and Abandon n Plug Back	Temporari Water Disp	ly Abandonoosal	
Describe Proposed or Completed Operation (clearl If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations: testing has been completed. Final Abandonment I determined that the final site is ready for final inspiration of the involved operations. TD-3855' PBTD-2625' PERFS 13-3/8" 48# @ 242' w/ 175sx, 17-1 8-5/8" 32# @ 1240' w/ 400sx, 11" 5-1/2" 17# @ 3855' w/ 350sx, 7-7/ 1. RIH & Tag CIBP @ 2625' 2. M&P 25sx cmt @ 2625-2500' 3. Perf @ 1290' sqz 80sx cmt to 4. Perf @ 292' sqz 125sx to Surf 10# MLF BETWEEN PLUGS	plete horizontally, give surformed or provide the Bif the operation results in Notices shall be filed onlection) 6-2675-3495' 6-2675-3495' 6-2675-3495' 6-2675-3495' 7-4" hole, TOC-Surf-Company to the Bif the Surf-Company to the Surf-Company	absurface locations and mean ond No. on file with BLM/ a multiple completion or rely after all requirements, and CIBP-2625'	SEE A COND	tical depths of all pertinent markers and zones ubsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once	
14. I hereby certify that the foregoing is true and correct Name (Printed Typed) David Stewart			gulatory Ana	alyst	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the conduct operat	those rights in the subje	TitbISTRIC urant or office of lease	I 1 SUPER	RVISOF Date MAY 1 3 2009	

Occidental Permian Ltd. Gillully B Federal RA A #6Y API No. 30-025-06201



Occidental Permian Ltd. - Proposed Gillully B Federal RA A #6Y API No. 30-025-06201

125sx @ 292'-Surface

17-1/4" hole @ 242' 13" csg @ 242' w/ 175sx-TOC-Surf-Circ Perf @ 292' 11" hole @ 1240' 8-5/8" csg @ 1240' w/ 400sx-TOC-Surf-Circ Perf @ 1290'

80sx @ 1290-1100' WOC-Tag

25sx @ 2625-2500'

12/08-CIBP @ 2625'

12/96-CIBP @ 3574' w/ 35' cmt-Pkr @ 3575'

9/54-CR @ 3767'sqz w/ 100sx cmt

7-7/8" hole @ 3776' 5-1/2" csg @ 3776' w/ 350sx-TOC-1755'-Calc

Perfs @ 3730-3756'

TD-3855

Perfs @ 2675-3495'

4-3/4" OH @ 3776-3855'

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed prior to commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.