Office	tate of New Mexico	Form C-103
District I Energy, M	linerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CON	NSERVATION DIVISION	30-025-38662
1301 W. Gland A.C., Altesia, 100 502 10	South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	anta Fe, NM 87505	STATE FEE X
0131176117	anta Fe, Nivi 6/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		N/A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Hester 12
1. Type of Well: Oil Well X Gas Well Other		8. Well Number 010
2. Name of Operator		9. OGRID Number
2. Name of Operator Apache Corporation		00873
3. Address of Operator 6120 S Yale Ave, Suite 1500 Tulsa, OK 74136-4224		10. Pool name or Wildcat
		House; Bli, S / House; Tubb / House; Dri
4. Well Location		
	from the South line and 165	
	ship 20S Range 38E	NMPM County Lea
	Show whether DR, RKB, RT, GR, etc.	
3,569' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO	D: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND AB	ANDON 🗌 REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON CHANGE PLAI	NS 🗌 COMMENCE DR	ILLING OPNS. P AND A
PULL OR ALTER CASING	MPL CASING/CEMEN	T JOB 🔲
DOWNHOLE COMMINGLE		
OTHER.	OTHER: Re-Com	nlation Procedure [7]
OTHER: 13 Describe proposed or completed operations		pletion Procedure A give pertinent dates, including estimated date
13. Describe proposed or completed operations.	(Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE	(Clearly state all pertinent details, an	
13. Describe proposed or completed operations.	(Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.	(Clearly state all pertinent details, an	d give pertinent dates, including estimated date
 Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 	(Clearly state all pertinent details, an	d give pertinent dates, including estimated date
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH.	d give pertinent dates, including estimated date
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W 	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An III POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 	(Clearly state all pertinent details, an 1103. For Multiple Completions: At ID POOH. RIH W/ TBG TO 7138'.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W 	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An III POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An ID POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE RIGHT REPORT OF THE PROPURCY OF THE P	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD.
 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W 	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An ID POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE RIGHT REPORT OF THE PROPURCY OF THE P	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD.
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An ID POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE RIGHT REPORT OF THE PROPURCY OF THE P	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD.
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An ID POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE RIGHT REPORT OF THE PROPURCY OF THE P	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD.
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W Spud Date: 08/02/2008 I hereby certify that the information above is true and SIGNATURE SIGNATURE SEE RULE ACCUMANTALE WAS AND PUMP (STORT AND PUMP) 10/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W Spud Date: 08/02/2008	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An ID POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE Complete to the best of my knowledge TITLE Engineering Tech	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD. e and belief. DATE 02/19/2009
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W Spud Date: 08/02/2008 I hereby certify that the information above is true and SIGNATURE Sophic Mackay Type or print name Sophic Mackay	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An ID POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE Complete to the best of my knowledge TITLE Engineering Tech	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD.
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W Spud Date: 08/02/2008 I hereby certify that the information above is true and SIGNATURE SIGNATURE SEE RULE ACCUMANTALE WAS AND PUMP (STORT AND PUMP) 10/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W Spud Date: 08/02/2008	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An 1103. For Multiple Completions: An 1104 POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD. e and belief. DATE 02/19/2009 tapachecorp.comPHONE: (918)491-4864
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/08 - 12/29/08 PUMP TESTING BLINEBRY. 12/30/08 POOH W/ RODS AND PUMP. 12/31/08 - 01/03/09 RELEASE RBP @ 6500' AN 01/05/09 RELEASE RBP @ 6920' AND POOH. 01/06/09 RIH W/ PUMP AND RODS. PLACE W Spud Date: 08/02/2008 I hereby certify that the information above is true and SIGNATURE Sophic Mackay Type or print name Sophic Mackay	(Clearly state all pertinent details, an 1103. For Multiple Completions: An 1103. For Multiple Completions: An ID POOH. RIH W/ TBG TO 7138'. VELL ON PRODUCTION FROM THE Complete to the best of my knowledge TITLE Engineering Tech	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion HE BLINEBRY/TUBB/DRINKARD. e and belief. DATE 02/19/2009 tapachecorp.comPHONE: (918)491-4864