## State of New Mexico Energy, Minerals and Natural Resources Department

Form C 103 Revised 1-1-89

OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM S8240 WELL API NO. P.O. Box 2088 30-025-20977 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE •APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Well X State A A/C 1 OTHER 8. Well No. 2. Name of Operator Raptor Resource 109 9. Pool name or Wildcat 3. Address of Operator Jalmat Tansill Yates 7 Rvrs (Gas)79240 901 Rio Gram 4. Well Location North East 560 Unit Letter A Feet From The Line Feet From The Line and County **NMPM** Section **23S** Township Range 36E 10. Elevauon (Show whether DF, RKB. RT, GR, ctc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ALTERING CASING PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE SCININING OF Rantor Resources. Inc plans to P&A the aaabove listed well per the following procedure JUMP PLUGGING OPERATIONS FOR THE C-103 1. Set CIBP @ 2920' with 5 sx cement on top. BAILEDTO BE APPROYED 2. Perf 4 1/2" csg @ 2550 3. Squeeze perfs W/35 sk cement plug (100' in, 100' out). 4. WOC 4 hrs. Tag plug @ 2450'. 5. Perf 4 1/2" csg @315'. 6. Circ 150 sx cement plug to surface through 7 5/8" csg. 7. Cut off wellhead - weld on P&A marker. 8. Clean off location for OCD inspection. 12. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **Agent For Raptor Resources** 12/19/03 TELEPHONE NO. 432-697-1609 TYPE OR PRINT NAME Bill R. Keathly OC FIELD REPRESENTATIVE INSTAFF MANAGER (this space for State Use)