
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE RECEIVED CONSERVATION DIVISION	,
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 JUN 0 5 2009 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-29276
·	5 Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88 10 OBBSOCD	STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) 1. Type of Well.	Section 28 8. Well No. 242
Oil Well Gas Well Other Injector	5, 15, 15, 15, 15, 15, 15, 15, 15, 15, 1
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	10 Pool name or Wildcat Hobbs (G/SA)
3: Address of Operator HCR 1 Box 90 Denver City, TX 79323	10 Pool name or Wildcat Hobbs (G/SA)
4. Well Location	
Unit Letter N : 1166 Feet From The South Line and 1823 Feet	et From The West Line
Section 28 Township 18-S Range 38-I	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3644' GR	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or ONOTICE OF INTENTION TO:	Other Data SEQUENT REPORT OF:
1101102 01 11112111011101	SEQUENT REPORT OF.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
THE THE STATE OF T	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING INS. PLUG & ABANDONMENT NT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing	ALTERING CASING PLUG & ABANDONMENT NT JOB Integrity Test X.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test S, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates)	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test S, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test S, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes	ALTERING CASING NS. PLUG & ABANDONMENT NT JOB Integrity Test s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Casing Test and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes Witnessed: YES – Buddy Hill - NMOCD	ALTERING CASING PLUG & ABANDONMENT NT JOB Integrity Test S, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion OTHER: Casing OTHER: O6/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes Witnessed: YES – Buddy Hill - NMOCD	ALTERING CASING PLUG & ABANDONMENT NT JOB Integrity Test X s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes Witnessed: YES – Buddy Hill - NMOCD 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PLUG & ABANDONMENT NT JOB Integrity Test X s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes Witnessed: YES – Buddy Hill - NMOCD 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING PLUG & ABANDONMENT NT JOB Integrity Test S, including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be be OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes Witnessed: YES – Buddy Hill - NMOCD 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 1 further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan. SIGNATURE MULTIPLE Administrative.	ALTERING CASING PLUG & ABANDONMENT Integrity Test Integrity
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEMENT OTHER: OTHER: OTHER: OTHER: OTHER: Casing OTHER: Casing OTHER: OTHER: Casing OTHER: OTHER: OTHER: OTHER: Casing OTHER: OTHER: OTHER: Casing OTHER: OTHE	ALTERING CASING PLUG & ABANDONMENT Integrity Test Integrity
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion THER: Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes Witnessed: YES – Buddy Hill - NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative mendy johnson@oxy.com For State Use Only PLUS AND ABANDON COMMENCE PRILLING OP CASING TEST AND CEMENT OF CASING TEST AND CEMENT OTHER: Casing OTHER: OTHER: Casing OTHER: DATE AND CEMENT OF CASING TEST AND CEMENT OTHER: DATE AND CEMENT OTHER:	ALTERING CASING PLUG & ABANDONMENT Integrity Test Integrity
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEMENT OTHER: Casing DIAL Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Test Date: 06/01/2009 Pressure Reading: Initial – 510 PSI; 15 min – 510 PSI; 30 min – 500 PSI Length of pressure test: 30 minutes Witnessed: YES – Buddy Hill - NMOCD Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative plan SIGNATURE Mendy Johnson E-mail address: mendy johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT Integrity Test Integrity



त्यात्रकार प्राप्तेत्रकेषुं प्राप्त्रकारका स्वयावस्य विश्वतिकार्यकेषुं केर्नात्रकार केर्