

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.
Director

Oil Conservation Division

24-Jun-09

PLATINUM EXPLORATION INC

550 WEST TEXAS AVENUE SUITE 500 MIDLAND TX 79701-

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

	IDLE WELL INSP	PECTION DETAIL SECT	TION	
BARNHILL 001	L-1-14S-37E	30-025-28198-00-00	Inspection No. iMGB0917559776	
Inspection Date: 6/24/2009 4:36:16 PM		Correc	Corrective Action Due by: 7/27/2009	
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	
Routine/Periodic	Maxey Brow	yn Yes	No	
Comments on Inspection:	PROD REPORTED IN 31 1ST LETTER OF NON-C	MONTHS. NEED TO INSTA OMPLIANCE.	TO PROD., T/A, OR P/A WELL. NO LL WELL SIGN RULE 19.15.16.8. THIS I	
POST 002	M-1-14S-37E	30-025-28295-00-00	Inspection No. iMGB0917558556	
Inspection Date: 6/24/2009 4:15:56 PM		Correc	Corrective Action Due by: 7/27/2009	
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	
Routine/Periodic	Maxey Brow	yn Yes	No	
Comments on Inspection:		MONTHS. NEED TO INSTA	OD., T/A, OR P/A WELL. NO PROD LL WELL SIGN (RULE 19 15.16 8) THE	

POST 003

D-12-14S-37E

30-025-28576-00-00

Inspection No. iMGB0917559026

*Significant Non-Compliance?

Inspection Date:

6/24/2009 4:23:46 PM

Corrective Action Due by: 7/27/2009

Type Inspection

Inspector

Violation?

Routine/Periodic

Maxey Brown

Yes

Comments on Inspection:

Idle Well (Rule 19 15.25.8) NEED TO RETURN TO PROD., T/A, OR P/A WELL. NO PROD REPORTED IN 46 MONTHS. ALSO NEED TO REMOVE OIL FROM CELLAR. RULE 19.15.29 8. CORRECT LEAK AND FILL IN CELLAR TO KEEP LIVSTOCK OUT. RULE 19.15.29.11. THIS IS 1ST LETTER OF NON-COMPLIANCE.

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infra-

structure of the oil and gas industry.

Sincerely,

Hobbs OCD District Office

COMPLIANCE OFFICER

^{*} Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



PLATINUM EXPLORATION INC 550 WEST TEXAS AVENUE SUITE 500 MIDLAND TX 79701