Form 3160-5 (August 1999)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED OMB No 1004-0135 Expires November 30,2000

5 Lease Senal No

SUNDRY NOTICES AND REPORTS ON WELLS					LC-069515	
Do not use this form for proposals to drill or to re-enter an					Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals						
OUDIUS IN TO	IDLICATE Other le	atriotions on roys	reo cido	7 If Unit or	CA/Agreement, Name and/or	
SUBMIT IN TRIPLICATE - Other Instructions on reverse side					No	
					North El Mar Unit	
1 Type of Well				8 Well Nan	0994X	
Oil Well Gas Well Other  Name of Operator					El Mar Unit #10	
Sahara Operating Company			9 API Well	No /		
3a Address 3b. Phone No. (u			e area code)		025 08299 🗸	
P.O. Box 4130, Midland, TX 79704 432/697-0					Pool, or Exploratory Area	
4 Location of Well (Foolage, Sec., T, R, M, or Survey Description)					ar (Delaware)	
1980' FNL & 1980' FWL, Sec 26, T26S, R32E, NMPM				I	ounty, N.M.	
Unit Letter "F"						
12. CHECK APPR	ROPRIATE BOX(ES) T				R OTHER DATA	
TYPE OF SUBMISSION		T	YPE OF ACTION	N		
K	Acidize	Decpen	P	roduction (Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treatmen	t 🔲 R	Leclamation	Well Integrity	
Subsequent Report	Casing Repair	☐ New Construction	R	Lecomplete	Other	
	Change Plans	Plug and Abandor	П Т	emporanly Abandon		
Innal Abandonment Notice	Convert to Injection	Plug Back		Vater Disposal		
13 Describe Proposed or Completed Of the proposal is to deepen direct	ionally or recomplete horizontally	y, give subsurface locations an	d measured and true	vertical depths of all pert	inent markers and zones. Attach the	
Bond under which the work will be	e performed or provide the Bond	No on file with BLM/BIA R	equired subsequent	reports shall be file within	30 days following completion of the testing has been completed. Final	
Abandonment Notices shall be filed	ion results in a mutiple complet I only after all requirements, inclu	ition of recompletion in a new iding reclamation, have been co	merval, a rottl 3 mpleted, and the op	erator has determined that	the site is ready for final inspection)	
Propose to P&A: 1. S	pot 25 sx on CIBP	@ 4480'		" See At	tached COA's"	
2. C	irc hole with mud			200		
3. Perf 980', sqz 35 sx 880'-980' WOC 727					DEPENIER	
4. Perf 380', Sqz 35 sx 280'-380' woc Tag					RECEIVED	
5. Perf 60', fill in/out					JUN 26 2009	
6. Install dry hole marker					_	
•					HOBBSOCO	
Wellbore as follows: Casing: 7-5/8" @ 330' w/125 sx, circ						
4-1/2" @ 4582' w/700 sx, TOC 1090' by temp survey						
		535'; CIBP: @			•	
14 I hereby certify that the force			<u>, , , , , , , , , , , , , , , , , , , </u>			
Name (Printed/Typed)						
Robert McAlpine			le Pres	sident		
. 1	11/1/1/1/1					
Signature Date 6-10-2009						
THE SPACE FOR FEDERAL OR STATE OFFICE USE						
	00		THE PL	21	Date 6-23-09	
Approved by Conditions of approval if any are att	Title SE	<u> </u>	Date 2 2 7			
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the Office						
applicant to conduct operations thereon		lease which would entitle the	Office /	^)		
··· / / ···		lease which would entitle the	Office Cf	<i>D</i>		

N. El Mar vair	920
HOLE SIZE ///	Perfælo's suf BASE 4256 Circito Suf RILLE T
2,4	SPEC WASER
CASING SIZE 75/0" H-40 11/1/17 TD 330 HOLESIZE	Perf@ 380 SO From 380-280 WOC Tag
221 13. 13. 13. 13. 13. 13. 13. 13. 13. 13	FORMATIONS Dec. 4479
70C 1090	Perf @ 980 SQ from 980 - 880
700 Sx Cmf	WOC. Tag
CASING SIZE 4/2 J-55	25 SX Plug CIBP@ DVT
CACING SIZE 4/2 J-55	4480 PERFORATIONS 4529-453

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed prior to commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.



## United States Department of the Interior

### BUREAU OF LAND MANAGEMENT

' Carlsbad Field Office 620 E Greene St Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To 1310

#### Reclamation (Interim/Final) Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5. Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979