

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

RECEIVED**JUL 14 2009****HOBBSOCD**

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. ☒

30-025-34154

5. Indicate Type of Lease

STATE ☒ FEE ☐ ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement
NameHood State ☒8. Well Number 1 ☒9. OGRID Number 240974 ☒10. Pool name or Wildcat
Cam; Devonian ☒

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☒2. Name of Operator LEGACY RESERVES OPERATING LP ☒3. Address of Operator P.O. BOX 10848
MIDLAND, TX 79702

4. Well Location

Unit Letter F : 2250 feet from the North line and 2310 feet from the West line.Section 25 Township 10S Range 37E NMPM Lea County ☒

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3918' GR; 3936' KB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐OTHER: Temporarily Abandon and MIT Test ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

----- See Attached -----

7/8/09 – Ran MIT test with starting pressure of 625 psi and final pressure of 620 psi for 30 min., held.
Test witnessed and chart signed by Maxy Brown with NMOCD. Chart attached.

This Approval of Temporary
Abandonment Expires 7-15-2014

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE D. Patrick Darden TITLE: Senior Engineer DATE 07/13/09Type or print name D. Patrick Darden, P.E. E-mail address: Telephone No. (432) 689-5200**For State Use Only**


APPROVED BY: [Signature] TITLE DISTRICT 1 SUPERVISOR DATE JUL 15 2009
Conditions of Approval (if any):

TEMPORARILY ABANDON WELL
Subsequent Report Form C-103
Hood State #1

Started 6/30/09

- 1) MIRU PU. RU pmp trk. Press tst TCA to 500 psi. Held. Rel press.
- 2) Rel pkr. ND WH. NU BOP. POH w/pkr.
- 3) PU & RIH w/CIBP to 11,818'. Set CIBP @ 11,818'. Dumped 4sx cmt on CIBP.
- 4) PUH, mixed, ppd & circ'd 260 bbls inhibited wtr. Press csg to 500 psi, held.
- 5) POH LD tbg. ND BOP. NU WH.
- 6) RU chart recorder. RU pmp trk. Press tst csg with starting pressure of 625 psi & final pressure of 620 psi for 31 minutes. Held. Tst witnessed & chart signed by Maxy Brown with New Mexico OCD.
- 7) Well TA'd.

Work completed: 7/08/09.



D. Patrick Darden

D. Patrick Darden, PE #75593

