Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> 1625 N. French Dr , Hobbs, NM 88 <u>240</u>	Energy, Minerals and Natural Resources	WELL API NO. June 19, 2008
District II 1301 W. Grand Ave., Artesia, NM 882 CENTRON SERVATION DIVISION		30-025-03399
		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 874 1001 17 1004 Santa Fa NM 87505		STATE X FEE 6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, N	SOCO	o. State on & Gas Lease No.
Part	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A FION FOR PERMIT" (FORM C-101) FOR SUCH	Mexico W
1. Type of Well: Oil Well 🔯 Gas Well 🖂 Other		8. Well Number 4
2. Name of Operator Chesapeake Operating, Inc.		9. OGRID Number 147179
3. Address of Operator P.O. Box 18496 Oklahoma City, OK 73154-0496		10. Pool name or Wildcat  Eumont; Yates-Seven Rivers-Queen Oil
4. Well Location		
Unit Letter 1: 3300' feet from the North line and 660' feet from the East line		
Section 2 Township 21S Range 35E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3573' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	PLUG AND ABANDON   REMEDIAL WO	ORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING ☐ N DOWNHOLE COMMINGLE ☐	MULTIPLE COMPL   CASING/CEME	INT JOB
DOWNINGE COMMINGEE		
OTHER.	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
The following work was performed in the plug and abandonment of this well from 7/9/09 through 7/14/2009.		
MIRU PU. POOH w/rods, pump & tubing. NDWH & NUBOP. RIH w/gauge ring to 3,275'. CIBP.set @ 3,275' & circ brine & mud.		
Dumped 45 sxs cmt from 3,275'-2,841'. WOC & tag plug @ 2,837', Perf 1657' & RIH w/ packer @ 1,234'. Load hole, inj rate 750 psi.		
1 bbl/min, sqzd 40 sxs cmt from 1,657'-1,557'. SI press 500 psi. Release pkr, POOH w/tbg & pkr, tag plug @ 1,546'. Perf @ 376' &		
set pkr @ 30', est circ between 5 1/2 & 8 5/8, hole in 8 5/8 @ WH. Sqzd 100 sxs @ 376', stopped circ after 80 sxs. Did not regain. Displaced TOC @ 100'. Lay down pkr & tbg. Tag plug @ 90' & perf 68'. Set pkr @ 30' & sqz 15 sxs cmt. Lay down pkr. Top off		
w/cmt. RDMO. Prepare location for final clean up.		
Well P&A'd on 7/14/09.  Approved for plugging of well bore only.		
	Liat of C	bility under bond is retained pending receipt 2-103 (Subsequent Report of Well Plugging)
	[ Whi	ch may be found at OCD Web Page under
		no, www.mirtustate:nm:45/0cd.
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE TITLE Senior Regulatory Compl. Sp. DATE 07/16/2009		
Type or print name Bryan Arrant E-mail address: bryan.arrant@chk.com PHONE: (405)935-3782		
For State Use Only		
DISTRICT 1 SUPERVISOR		
APPROVED BY: Conditions of Approval (if any):	TITLE	DATE_JUL 2 0 2009