

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
OCD HOBBS

FORM APPROVED
OMB NO. 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

JUL 17 2009

HOBBSOCD

SUBMIT IN TRIPLICATE - Other instructions on page 2

1 Type of Well

☐ Oil Well

☐ Gas Well

☒ Other Injection

2. Name of Operator

Stephens & Johnson Operating Co.

3a Address

P.O. Box 2249 Wichita Falls TX 76307-2249

3b. Phone No. (include area code)

(940) 723-2166

4 Location of Well (Footage, Sec., T, R, M, or Survey Description)

Sec 35, T14S, R37E

1980' FNL & 460' FEL

unit - H ✓

5 Lease Serial No

6 If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.
8910087370

Denton North Wolfcamp Unit

8 Well Name and No

Denton North Wolf- Tr 6-30

camp Unit

9 API Well No

30-025-05201

10. Field and Pool, or Exploratory Area

Denton Wolfcamp

11 County or Parish, State

Lea County

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

P&A June 2009

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

6-9-2009 Tag existing CIBP @ 8490'. Circ. hole w/mud. Perf. @ 6500'. Pressure test to 2200 psi.. Held. Spot 35 sx. cmt @ 6562'. Tag plug @ 6122'.

6-10-2009 Perf @ 4828'. Pressure test to 2000 psi, held. Spot 50 sx cmt. @ 4878'. Tag plug @ 4405'. Spot 35 sx cmt @ 3150-2978'. Spot 45 sx cmt @ 2250'. Tag plug @ 2042'.

6-11-2009 Perf @ 510'. Squeeze 60 sx cmt @ 510'. Tag plug @ 282'. Perf @ 60'. Squeeze 40 sx.to surface out of 10 3/4" csg. Leave 7 5/8" full of cmt.

6-12-2009 Install Dry hole marker.

**Note: This well is a State well; however, Tract 1 is Federal. Therefore we respectfully request that the BLM update the well status in their database.

ACCEPTED FOR RECORD

JUL 15 2009

/s/ JD Whitlock Jr

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

FEE well needs STATE Approval

14 I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Devire D Crabb

Title Production Analyst

Signature

Devire D. Crabb

Date June 30, 2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

[Signature]

DISTRICT 1 SUPERVISOR

Date JUL 20 2009

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.