

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural ResourcesOIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505WELL API NO.
3000500674

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

E-8665

7. Lease Name or Unit Agreement Name
SOUTH CAPROCK QUEEN UNIT

8. Well Number

003

9. OGRID Number

12627

10. Pool name or Wildcat

8559 CAPROCK QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Kevin O. Butler and Associates, Inc.

3. Address of Operator

P. O. Box 1171; Midland, TX 79702

4. Well Location

Unit Letter C 330 feet from the NORTH line and 1633 feet from the EAST line Section 31 Township 15S Range 31E
NMPM CHAVES County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐OTHER: ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9 5/8 SURFACE CSG SET @245'. CMT CIRC 5 1/2" PROD CSG SET @3059' TOC?
PERFS 2991' - 2998' TOS 1200' BOS 2078'.

- MIRU TO P/A WELL.
- COULD NOT GET PKR BELOW 1800' WHILE CHECKING CASING INTERGRITY REQUEST FOREGO CIBP AND REPLACE WITH 25 SACKS OF CEMENT ACROSS PERFS
- CIRC HOLE W/MFL (9.5 PPG BRINE 7W/125.5 LLBS PER BBL OF SALT GEL.
- PERF AT 2100', SQZ 25 SXS CMT. WOC AND TAG (BOS PLUG).
- PERF AT 1150', SQZ 25 SXS CMT. WOC AND TAG (TOS PLUG).
- PERF AT 295', (50' BELOW SURFACE SHOE). SQZ 25 SXS CMT AND WOC AND TAG AT 195' OR SQZ SUFFICIENT CMT INSIDE AND OUTSIDE TO CIRC TO SURFACE. (SHOE AND SURFACE).
- CUT OFF WELLHEAD AND ANCHORS, INSTALL DRY HOLE MARKER.
- CLEAN LOCATION.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE President/Owner

DATE 07/28/2009

Type or print name Kevin O. Butler E-mail address: Lisa@geedmidland.com PHONE: 432-682-1178 For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

30-005-00674

KEVIN O BUTLER & ASSOCIATES

SOUTH CAPROCK QUEEN UNIT #003

C-31-15-31

PRESENT

