Form 3160-5 (August 2007)	DEPARTME	TED STATES NT OF THE INTERI LAND MANAGEM		OCD	-HOBBS	OM	RM APPROVED IB NO 1004-013 pires July 31, 2010	7	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS						5. Lease Seriet No			
	o not use this form for andoned well. Use For	proposals to drill	or to re-enter			6 If Indian, Al	llottee or Tribe Na	ime	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No 8910087370				
1. Type of Well Gas Well OI Well Gas Well 2. Name of Operator Injection						8. Well Name and No DNWC TR 14 Well #3			
Stephens & Johnson Operating Co.					and al	9. API Well No			
3a. Address P.O. Box 2249, Wichita Falls, TX 76307-2249			3b Phone No (<i>include area code</i>)			<u>30-025-051</u>	.30 Pool, or Explorate		
4. Location of Well (Footage, Sec, T., R., M., or Survey Description) Unit Letter F 1980' FNL & 2180' FWL Sec 26 T14S R37E						n' WƏIFC Parish, State	amp		
12.	CHECK APPROPRIATI	E BOX(ES) TO IN	DICATE NATU	RE OF NO	TICE, REPC	RT, OR OTHE	ER DATA		
TYPE OF SUBMISSION TYPE OF ACTIO					OF ACTION				
X Notice of	of Intent	Acıdıze	Deepen Fracture		Production Reclamation	ı (Start/Resume)	Water Shut-G		
	ent Report vandonment Notice	Casing Repair New Construction Recom			Recomplet				
		Convert to Injects			Water Disp		Abandon		
If the proposal is to Attach the Bond un following completio testing has been co	or Completed Operation (clearl deepen directionally or recomp ider which the work will be pe in of the involved operations. I mpleted Final Abandonment I final site is ready for final inspe	blete horizontally, give s formed or provide the f the operation results Notices shall be filed or	subsurface location Bond No. on file in a multiple comp	s and measur with BLM/BI letion or reco	ed and true ver A. Required s moletion in a r	rtical depths of al subsequent report new interval, a Fe	ll pertinent marker ts shall be filed w orm 3160-4 shall	rs and zones. 1thin 30 days be filed once	
Request tempo	MIT on well. Pressu prary abandonment for I in place with State	5 years for po	ssible use i	-		pressure cl od. One we			
Please note: update this w	Well is "State" we Well status in their		act 1 is "Fe	deral".	Therefore	e, we reque	st that the	BLM	
						CEPTED) FOR RE	CORD	
JUL Z A ZURA									
HOBBSOCD					,	2 7 2009 Whitlock	Jr		
							LAND MANAG		
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Devire D Crabb			Title	Tule Production Analyst					
Signature	if crean		Date 6	-6-09	 .			~	
	THIS	SPACE FOR FED	ERAL OR STA	TE OFFIC	CE USE				
Approved by Conditions of approval, if any,	, are attached Approval of this noti	ce does not warrant or cert		TRICT 1	SUPER	VISOR J	"ŋ[30;	2009	
the applicant holds legal or eq entitle the applicant to conduc	uitable title to those rights in the sub	yect lease which would		lifully to make	to any department	nt or agency of the	United States any fa	lse.	
	ents or representations as to any ma		and and w			or agoing of the	oraco any m	-,	

MIJENS

. 1

	WIJGH3			
Subfruit 3 Copies To Appropriate District State of New Mexico	Form C-103			
- Office Energy, Minerals and Natural Resources District I 1625 N French Dr. Hobbs, NARCEIVED District II	June 19, 2008			
District.II No Anna Advisor Anna Advisor Anna Advisor OIL CONSERVATION DIVISION	30-025-05130			
District III IAY 0 4 7000 1220 South St. Francis Dr.	5. Indicate Type of Lease			
District IV HORKSOCD	STATE FEE 6. State Oil & Gas Lease No.			
1220 S St Francis Dr., Santa Fe, NM 87505	6. State OII & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: Denton North Wolfcamp			
PROPOSALS.) 1. Type of Well:	Agree #8910087370 8. Well Number			
- Oil Well Gas Well Other injection	Tract 14, Well #3			
	9. OGRID Number			
Stephens & Johnson Operating Co.	019958			
P.O. Box 2249, Wichita Falls, TX 76307-2249	Denton Wolfcamp			
4. Well Location				
Unit Letter F: 1980 feet from the North line and	2180 feet from the West line			
Section 26 Township 14S Range 37E	NMPM County Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.				
12. Check Appropriate Box to Indicate Nature of Notice, R				
NOTICE OF INTENTION TO: SUBS PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLIN PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOIN DOWNHOLE COMMINGLE - -				
OTHER OTHER temporaril	y abandon			
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompletion. 1-8-09: Ran MIT on well. Pressure testing cssg. Witnessed by OCD. Request for temporary abandonment for 5 years for possible to One well plugging bond in place. 	pertinent dates, including estimated date wellbore diagram of proposed completion OCD took pressure chart.			
This Approval of Temporary Abandonment Expires				
Spud Date: Rig Release Date:				
I hereby certify that the information above is true and complete to the best of my knowledge a	and belief			
SIGNATURE OF STATE TITLE Petroleum I				
bgilmore@sjoc Type or print name <u>Bob Gilmore, P.E.</u> E-mail address:				
For State Use Only APPROVED BY Any W. Lef TITLE				
Conditions of Approval (if any):				

.

