Form 3160-5	
(August 2007)	
(August 2000)	A Company

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREALLOE LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No NMNM24683  Do not use this form for proposals to drill or to re-enter an OBBS Daylordoned well. Use form 3160-3 (APD) for such proposals.  5. Lease Serial No NMNM24683  6. If Indian, Allottee or Tribe 1	310
Do not use this form for proposals to drill or to re-enter all  6. If Indian, Allottee or Tribe 1	
	me

HOBBS (Mondoned well. Use form 31	6. If Indian, Allottee of Tribe Name	
SUBMIT IN TRIPLICATE - Other	7 If Unit or CA/Agreement, Name and/or No	
Type of Well	~	8 Well Name and No MultipleSee Attached
2 Name of Operator CHESAPEAKE OPERATING INC   E-Mail:	Contact LINDA GOOD linda.good@chk.com	API Well No     MultipleSee Attached
3a Address P O BOX 18496 OKLAHOMA CITY, OK 73154-0496	3b Phone No (include area code) Ph: 405.935.4275 Fx: 405.849.4275	10 Field and Pool, or Exploratory UNDESIGNATED
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)	11. County or Parish, and State
MultipleSee Attached		LEA COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	ISSION TYPE OF ACTION			
Notice of Intent  Subsequent Report  Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☑ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

CHESAPEAKE, RESPECTFULLY, REQUESTS, PERMISSION TO RECOMPLETE THIS WELL PER THE FOLLOWING PROCEDURE:

- 1. MIRU PU. NDWH/NUBOP.
- 2. PRESSURE TEST CASING TO 2,000 PSI.
- 3. RU WIRELINE CO. RUN CBL FROM PBTD TO DV TOOL @ 6,999' W/2,000 PSI TRAPPED ON THE CASING.
- 4. PERFORATE BRUSHY CANYON 8,582-8,624' (42'), W/2 SPF (84 HOLES), 120 DEGREE PHASING USING CASING GUN, .4" PERF HOLES.
- 5. RIH W/PACKER ON 2 7/8" TBG TO 8,525'. SPOT ACID ACROSS PERFS AND PULL PACKER UP TO 8,500'.

14 Thereby certify t	For CI	nission #72272 verified by the HESAPEAKE OPERATING I for processing by KURT SII	NC, sent to th	e Hobbs	
Name (Printed/Typ	Name (Printed/Typed) LINDA GOOD Title SR. REGULATORY COMPLIANCE SPEC			MPLIANCE SPEC	
Signature	(Electronic Submission)  THIS SPA	Date ACE FOR FEDERAL O			APPROVED
Conditions of approval certify that the applicar	ISTOPHER WALLS  i, if any, are attached Approval of this rate holds legal or equitable title to those replicant to conduct operations thereor	notice does not warrant or lights in the subject lease	PETROLEUM	M ENGINEER	JUL 29 Date 07/24/20  CARLSBAD FIELD OFFICE

Fille 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #72272 that would not fit on the form

Wells/Facilities, continued

Agreement NMNM24683 NMNM24683

Lease NMNM24683 NMNM24683 Well/Fac Name, Number MERCHANT 8 FEDERAL 1

MERCHANT 8 FEDERAL 1

API Number 30-025-36318-00-S2

30-025-36318-00-S1

Location Sec 8 T22S R33E SESW 880FSL 1760FWL 32 24050 N Lat, 103 35488 W Lon Sec 8 T22S R33E SESW 880FSL 1760FWL 32 24050 N Lat, 103 35488 W Lon

## 32. Additional remarks, continued

REVERSE ACID BACK INTO TUBING. SET PACKER AND PRESSURE BACKSIDE TO 1000 PSI. ACIDIZE PERFS W/4,000 GAL 15% NEFE ACID DROPPING 125 PERF BALLS EVENLY THROUGHOUT JOB. DISPLACE ACID TO BOTTOM PERF. SI 30 MINS. FLOW/SWAB BACK ACID AND TEST. POH W/PACKER.

- 6. IF WARRANTED, FRAC BRUSHY CANYON PERFS PER FRAC RECOMMENDATION DOWN CASING (ANTICIPATE 75,000# SAND, 50 BPM). FLOW BACK WELL UNTIL IT DIES.
- 7. RIH W/2 7/8" TBG W/SN to 8,550' (ABOVE PERFS) AND TAC @ 8,500'. RIH W/PUMP AND RODS.
- 8. NDBOP/NUWH. RD MO.

## Merchant 8 Federal 1 30-025-36318 Chesapeake Operating Inc. July 29, 2009 Conditions of Approval REVISED

- 1. Notify BLM 575-393-3612 a minimum of 4 hrs. prior to starting work.
- 2. Surface disturbance beyond the existing pad must have prior approval.
- 3. Closed loop system required.
- 4. Due to H2S in the area operator to have H2S monitoring equipment on location.
- 5. A minimum of a 3M BOP is required and must be tested prior to any of the work performed down hole.
- 6. Casing pressure test (2000 psi) as proposed to be performed after setting CIBP at 11,700'
  - a. Drill out CIBP at 11,700'.
  - b. Spot 25 sxs cmt on CIBP at 12,059' to cover top of Wolfcamp formation and the top of liner. WOC min. 4 hrs. and tag plug at 11,930' or shallower. Top of Wolfcamp 11,982'
  - c. Set CIBP at 11,700' and bail 35' of cmt or spot 25 sxs on top.
- 7. Resume proposed procedure.
- 8. Subsequent sundry and completion report required.
- 9. When well is abandoned or prior to selling a plug must be set to cover top of Bone Spring Formation.
- 10. Subject to like approval by State due to state surface.

CRW 072909