Subtitit 3 Copies To Appropriate District Office		New Mexico		Form C-103	
<u>District I</u> 1625 N French Dr , Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	May 27, 2004	
District 11 1301 W Grand Ave., Artesia, NM 88210	OIL CONSERY	VATION DIVISION	30-025-38957		
District III		h St. Francis Dr.	5. Indicate Type of Lease STATE	FEE 🛛	
1000 R10 Brazos Rd , Aztec, NM 87410 <u>District IV</u>	Santa Fe, NM 87505			No.	
1220 S St Francis Dr, Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit A  Boyz Fee	greement Name	
PROPOSALS)  1. Type of Well: Oil Well  Gas Well  Other ,			8. Well Number 2		
2. Name of Operator  Mack Energy Corporation			9. OGRID Number	3837 /	
3. Address of Operator			I 0. Pool name or Wildca		
P. O. Box 960 Artesia, NM 88211-0960			Arkansas Junction; San A	Indres	
4. Well Location	1520	Foot			
Unit Letter B 150 feet from the North line and 1530 feet from the East line Section 30 Township 18S Range 37E NMPM County Lea 150					
Section 30 Township 18S Range 37E NMPM County Lea 7  I 1. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3741' GR					
Pit type Depth Groundwa		arest fresh water well Dis	stance from nearest surface water		
Pit typeDepth GroundwaterDistance from nearest fresh water well Distance from nearest surface water  Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A					
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB					
OTHER: OTHER					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
7/28/2009 Set CIBP @ 4800' w/35'cmt cap. Called Maxey Brown w/24hr notice on 7/27/09.					
7/29/2009 RIH tag @ 4765'. Set 35sx plug back to 4605'. Set plug from 2950-2685', set plug @ 1800' w/35sx wait and tag @ 1505', set surface plug 100' back to surface.					
Note: Building dry hole marker.	) surface.				
<b>5</b> ,					
	RECEIVED				
JUL 30 2009					
		—— HOBRPOC	D		
The Oil Conservation Division	on Must be notified				
24 hours prior to the beginning of plugging operations					
I hereby certify that the information a	above is true and complete	to the best of my knowledge	and belief. I further certify th	at any pit or below-	
grade tank has been/will be constructed or	11 m				
SIGNATURE June W.		TITLE Production Clerk		<u>37/29/09</u>	
Type or print name Jerry W. Sherre	<u>:II                                     </u>	-mail address: jerrys@macke	energycorp.com Telephon	e No. <u>(575)748-1288</u>	
APPROVED BY: DISTRICT 1 SUPERVISOR DATE AUG 0 3 2009					
APPROVED BY:					
Conditions of Approval (II ally):					