

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Occidental Permian Limited Partnership

157984

3a. Address

P.O. Box 50250 Midland, TX 79710-0250

3b. Phone No. (include area code)

432-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

390 FNL 660 FEL NENE(A) Sec 21 T20S R37E

5. Lease Serial No.

NM-62667

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Gillully B Federal #6Y

RA A

9. API Well No.

30-025-06201

10. Field and Pool, or Exploratory Area

Eumont Yates-SR-Qn

11. County or Parish, State

Lea

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Deepen

☐ Production (Start/Resume)

☐ Water Shut-Off

☐ Alter Casing

☐ Fracture Treat

☐ Reclamation

☐ Well Integrity

☐ Casing Repair

☐ New Construction

☐ Recomplete

☐ Other

☐ Change Plans

☒ Plug and Abandon

☐ Temporarily Abandon

☐ Convert to Injection

☐ Plug Back

☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

6/23/09 - RU Basic Coiled Tubing Unit, RIH w/ Tbg and tag CIBP @ 2626'. Circulate hole w/ 50bbls of 10# plugging mud. M&P 25sx C cmt @ 2626-2373'. POOH w/ Coiled tbg.

6/24/09 - Test casing to 1000 psi. RIH & Perforate @ 1290'. POOH. RIH w/ tbg & set packer. EIR @ 2bpm @ 1300 psi. Squeezed 80sx C cmt w/ 2% CaCl2 @ 1290'-1040'. WOC. RIH w/ WL and tagged cmt @ 1040'. RIH and perforate @ 292'. POOH. Establish circulation through the annulus, circulate 80sx C cmt @ 292' surface. RD MO

RECEIVED

AUG 04 2009

HOBBSOCD

ACCEPTED FOR RECORD

JUL 31 2009  
/s/ Chris Walls

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

David Stewart

Title

Sr. Regulatory Analyst

Date

7/15/09

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

DISTRICT 1 SUPERVISOR

Date

AUG 05 2009

Office