Submit 3 Copies To Appropriate District State of New Mexico	Form C-103	
Office Energy, Minerals and Natural Resources District I	WELL API NO.	
1625 N. French Dr., Hobbs, 182740 District II 1301 W. Grand Ave, Artesia, NM 88210 1220 South St. Francis Dr.	30-025-07540	
	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 100 Santa Fe, NM 87505	STATE X FEE .	
District IV 1220 S. St. Francis Dr., Sant DESCUE 87505	6. State Oil & Gas Lease No. A-2747	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State Land Sec. 32	
1. Type of Well: Oil Well X Gas Well Other	8. Well Number	
2. Name of Operator OXY USA INC.	9. OGRID Number 16696	
3. Address of Operator	10. Pool name or Wildcat	
P.O. Box 4294, Houston, TX 77210-4294 4. Well Location	Bowers:Seven Rivers	
Unit Letter 0 : 660 feet from the South line and	1980 feet from the East tine	
Section 32 Township 18-S Range 38-E	NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, et 3624' GR	c.)	
	Pomont on Other Date	
12. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data	
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON	ING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT J		
DOWNHOLE COMMINGLE	- <u> </u>	
DOWNINGE GOWNINGE		
OTHER: OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
See Attached		
Spud Date: Rig Release Date:		
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief.	
SIGNATURE Mark Stephens TITLE Reg. Comp. Ar		
The state of the Mank Chambana The state of	tephens@oxy.com PHONE <u>(713) 366-530</u> 3	
For State Use Only DISTRICT 1.8	UPERVISOR SEP 0.1 2009	
APPROVED BY TITLE Conditions of Approval (if any):	DATE	

Page 2 (C-103 Attachment)

Plug and abandon State Land Sec. 32 Well No. 6 as follows -

1/4/08 - 1/8/08:

MI x RUPU. NU BOP. RIH with 2-3/8" tubing (open ended) x tag existing CIBP at 3026'. Circulate hole clean. Cap CIBP with 25 sx. Cl. C. Pull uphole to 2450'. Spot 45 sx. cement x displace to 2100'. Pull uphole to 1400' x WOC. RIH with 2-3/8" tubing x tag top of plug at 2064'. Pull uphole to 1300'. Spot 35 sx. cement x displace to 950'. POOH x WOC. RIH with 2-3/8" tubing x tag top of plug at 980'. RIH with wireline x perforate 5-1/2" casing at 350'. Set packer at 30', establish injection rate of 2 BPM @ 250 psi, and squeeze perfs with 120 sx. cement. Circulate cement to surface through 8-5/8" casing valve and leave 5-1/2" casing full of cement to surface. POOH with packer. ND BOP, cut off wellhead, and install dry hole marker. RD x MO x clean location.

MAVERICK WELL PLUGGERS DAILY REPORT

DATE:

January 4, 2008

RECEIVED

JOB#

2-068 (P & A)

AUG 3 1 2009

COMPANY:

Pogo Producing Co.

HOBBSOCD

WELL NAME & NUMBER:

Stateland "32" #6

Rode crew to location. Spot rig Mat, rigged up Pulling Unit, opened Well -0- PSI, unflanged Well, Nipple up BOP, rigged up 2 3/8" TBG Tools, RIH w/ 2 3/8" TBG (open ended) tag existing C.I.B.P 3.026', SWI and SDFD.

Rig Hrs. 9.5 X \$275=	\$ 2,612.50
Travel Hrs. 3 X \$115=	\$ 345.00
BOP=	\$ 650.00
Trucking Hrs. 10.5 X \$95=	\$ 997.50
Work String 3,000' X \$.45=	\$ 1,350.00

Daily Cost:	\$ 5,955.00
Previous Cost:	\$ 0.00
Cumulative Cost:	\$ 5,955.00

SIGNED:

RECEIVED MAVERICK WELL PLUGGERS DAILY REPORT

AUG 3 1 ZUU9

HOBBSOCD

DATE:

January 7, 2008

JOB#

2-068 (P & A)

COMPANY:

Pogo Producing Co.

WELL NAME & NUMBER:

Stateland "32" #6

Rode crew to location. Spot rig Mat, rigged up Pulling Unit, opened Well -0- PSI, circulate hole, clean w/25sx Salt Gel (9.5 # Mud) cap CIBP w/25sx Class C Cement, pull up hole to 2,450 spot 45sx Cement, displace to 2,100, pull up to 1,400, wait on Cement, RIH w/ 2'3/8" TBG. Tag top of Cement Plug at 2,064', pull up hole to 1,300 spot 35sx, Cement displace to 950, pull out of hole w/TBS, wait on Cement, SDFD.

Rig Hrs. 10 X \$275=	\$ 2750.00
Travel Hrs. 3.5 X \$115=	\$ 402. 放
Cement 105 X \$16.00=	\$ 1,680.00
Salt Gel 25 X \$16.00=	\$ 625.00
Water=	\$ 1,644.00
Ca CI=	\$ 80.00

Daily Cost:	\$ 7,181.00
Previous Cost:	5,955.00
Cumulative Cost:	\$ 13,136.50

SIGNED:

RECEIVED

AUG 3 1 2009 HOBBSOCD

MAVERICK WELL PLUGGERS DAILY REPORT

DATE: January 8, 2008

JOB # 2-068 (P & A)

COMPANY: Pogo Producing Co.

WELL NAME & NUMBER: Stateland "32" #6

Rode crew to location. RIH w/ 2 3/8" TBG, tag top of Cement Plug at 980', POOH w/ TBG, RIH w/ Wire line, perforate 5 1/2" Casing at 350', RIH w/ Packer, set at 30', established injection rate at 2 BPM at 250 PSI, squeezed perforates w/ 120sx of Cement. Circulate Cement to surface through 8 5/8" Casing Valve (left 5 ½" Casing full of Cement to surface) POOH w/ Packer, Nipple down BOP, cut off Well Head, install Dry Hole Marker, rigged down pulling unit and P & A equipment, cleaned location, SDFD.

Rig Hrs. 10 X \$275=	\$ 2,750.00
Travel Hrs. 3.5 X \$115=	\$ 402.50
Cement 130 X \$16.00=	\$ 2,080.00
Pump Charge	\$ 450.00
Sqz. Packer	\$ 500.00
3 Loads Water	\$ 1,866.00
Welder Hrs. 2 \$60.00=	\$ 120.00
Dry Hole Marker	\$ 250.00

 Daily Cost:
 \$ 8,418.50

 Previous Cost:
 \$ 13,136.50

 Cumulative Cost:
 \$ 21,555.00

SIGNED: