

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

<b>RECEIVED</b> <b>SEP 03 2009</b> <b>HOBBSDOCD</b>		WELL API NO. / 30-025-39342	
CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		6. State Oil & Gas Lease No. NA	
1. Type of Well: <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other: <input checked="" type="checkbox"/>		7. Lease Name or Unit Agreement Name DC Hardy	
2. Name of Operator Apache Corporation		8. Well Number 10	
3. Address of Operator 6120 S Yale Ave, Suite 1500 Tulsa, OK 74136		9. OGRID Number <input checked="" type="checkbox"/> 00873	
4. Well Location Unit Letter P : 435 feet from the South line and 385 feet from the East line Section 20 Township 21S Range 37E NMPM County Lea <input checked="" type="checkbox"/>		10. Pool name or Wildcat Tubb O&G (Oil) & Drinkard.	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3485'			

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: Completion Procedure <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/30-8/3/09 Perf Drinkard @ 6570, 79, 94, 6605, 08, 25, 29, 34, 38, 50, 56, 69, 72, 78, 82, 95, 6705, 14, 6720 w/2 JSPF. 38 total holes. Acid Drinkard w/2500 gals 15%. Frac Drinkard w/15036 gal Dyna Frac. 9912 gal DF 35 w/8425# SLC 20/40 sd. 9912 gal DF 35 w/19824# SLC 20/40 sd. 12012 gal DF 35 w/33033# SLC 20/40 sd. 5796 gal DF 35 w/21445# SLC 20/40 sd. Spot 1k gal 15% HCl across Tubb perms. Flush w/5285 gal A35G. Set comp plug @ 6360.  
8/3/09 Perf Tubb @ 6132, 34, 36, 56, 59, 6206, 09, 13, 16, 37, 60, 63, 65, 67, 72, 86 and 6303 w/2 JSPF. 34 total holes. Spearhead 1k gals acid on form. Frac Tubb w/15078 gals DF25G. 10038 gals DF25G w/10038# SLC 20/40 sd. 9996 gals DF25G w/19992# SLC 20/40 sd. 7980 gals DF25G w/23940# SLC 20/40 sd. 6930 gals DF25G w/25295# SLC 20/40 sd. 7518 gals DF25G w/33831# SLC 20/40 sd. Flush w/5859 gals A10G.  
8/4/09 DO plug @ 6360. Wash sand to PBTD @ 6805.  
8/5/09 RIH w/prod tbg to 6737'. RIH w/pump and rods.  
8/6/09 Set 640 pumping unit. Place well on production from the Drinkard and Tubb O&G (Oil).

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Amber Cooke*

TITLE Production Engineering Tech

DATE 08/31/2009

Type or print name Amber Cooke

E-mail address: amber.cooke@apachecorp.com

PHONE: 918.491.4968

**For State Use Only**

APPROVED BY:

*[Signature]*

TITLE

**PETROLEUM ENGINEER**

DATE

**SEP 08 2009**

Conditions of Approval (if any):