



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

**\*Response Required – Deadline Enclosed\***

08-Sep-09

**LIME ROCK RESOURCES A, L.P.**

1111 BAGBY STREET SUITE 4600

HOUSTON TX 77002-

**LETTER OF VIOLATION - Inactive Well(s)**

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that the well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

1. Immediately restore the well(s) to production, injection or disposal as applicable.
2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.


In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

***IDLE WELL INSPECTION DETAIL SECTION***

<b>REEVES ADQ STATE 001</b>	<b>A-14-18S-35E</b>	<b>30-025-29648-00-00</b>	<b>Inspection No. iJRH0925157047</b>
<b>Inspection Date:</b>	<b>9/8/2009 3:50:42 PM</b>	<b>Corrective Action Due by: 12/12/2009</b>	
<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>
<b>Compliance Verification</b>	<b>John Harrison</b>	<b>Yes</b>	<b>No</b>
<b>Comments on Inspection:</b>	<b>Idle Well (Rule 19.15.25.8) WELL IS INACTIVE WITH NO PRODUCTION REPORTED IN 16 MONTHS. OPERATOR MUST ATTEMPT TO RETURN TO PRODUCTION. 1ST LETTER OF NON-COMPLIANCE.</b>		

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,




C.O.

Hobbs OCD District Office

\* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



HASLER	017H15554612	US POSTAGE
	<b>\$0.44</b>	
	09/09/2009	
	Mailed From 88240	

LIME ROCK RESOURCES A, LP  
1111 BAGBY STREET STE 4600  
HOUSTON, TX 77002