

Form 3160-5
(February 2005)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTRECEIVED
SEP 29 2009
HOBBSOCFORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

ECHO PRODUCTION, INC.

3a. Address

P.O. BOX 1210, Graham, TX 76450

3b. Phone No. (include area code)

(940) 549-3292

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' ENL & 1650' FEL, UNIT B SEC. 31 T 22 S R 32 E

5. Lease Serial No.

NM 106916

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

E. Livingston 31

Fed. 35

9. API Well No.

30-025-36912

10. Field and Pool, or Exploratory Area

Livingston Ridge; Delaware
S.E.

11. County or Parish, State

Lea County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

10-5-07 Notify B.L.M. voicemail to Cathy on 10-8-07.

10-8-07 Set CIBP @6,900'.

10-9-07 Spot 25 sx. cnt. - 6,900'-6,648'. Spot 25 sx. cnt. w/2% CaCl. @5,700'. W.O.C. & tag T.O.C. @ 5,389'. cut 5 1/2" csg. @5,000'.

10-10-07 P.O.H. w/5,000' csg.

10-11-07 Spot 50 sx. cnt. w/2% CaCl. @5,050'. Tag @4,849'. Spot 30 sx. @4,650'-4,540'. Spot 30 sx. 2,050' - 1,940'. Spot 30 sx. cnt. @1,060'-940'.

10-12-07 Tag T.O.C. @935'. Spot 40 sx. cnt. w/2% CaCl. @875'. W.O.C. & tag T.O.C. @685'. Circulate 15 sx. cnt. @60'- surface. Remove Wellhead & anchors. Install P & A markers. Backfill cellar. Cellar

Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.OCT 29 2009
ACCEPTED FOR RECORD14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

GARY EGGLESTON

Title

P & A SUPERV.

SEP 25 2009

Signature

Date 10-17-07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

DISTRICT 1 SUPERVISOR

Office

BUREAU OF LAND MANAGEMENT
CARLSBAD DISTRICT OFFICE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

SEP 30 2009