۲ ^۱		OCD-NODES				
Form 3160-5 (August 2007)	UNITED STATES		FORM APPROVED OMB No. 1004-0137			
DEF	ARTMENT OF THE INT EAU OF LAND MANAG		5. Lease Ser		July 31, 2010	
			NM 0250			
	IOTICES AND REPORT form for proposals to a			Allottee or Trib	e Name	
	Use Form 3160-3 (APD					
SUBMI	T IN TRIPLICATE – Other insi	tructions on page 2.	7. If Unit of	CA/Agreement,	, Name and/or No.	
1. Type of Well		1			/	
Gas W	Vell Other		8. Well Nan Texaco Fe	deral #2		
2. Name of Operator Tandem Energy Corp.			9. API Well 30-025-20	No. 189		
3a. Address 11490 Westheimer Road, Suite 1000 Houston, TX 77077		Phone No. <i>(include area c</i> 1-649-4571	· ·	d Pool or Explor en (Queen)	ratory Area	
4. Location of Well <i>(Footage, Sec., T.,</i> 330' FNL & 660' FEL	R., M., or Survey Description)	· · · · · · · · · · · · · · · · · · ·		or Parish, State		
NE / NE Sec1, T 20S, R34E	/		Lea Count	y, NM 🖌		
12. CHEC	CK THE APPROPRIATE BOX(E	ES) TO INDICATE NATU	RE OF NOTICE, REPORT	OR OTHER DA	ATA	
TYPE OF SUBMISSION		· T	YPE OF ACTION			
✓ Notice of Intent	Acidize	Deepen	Production (Start/I	Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction I Plug and Abandon	Recomplete	don.	_ Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	4011		
The approximate start date for P&A Please find the attached procedure Also please find a Well Bore Sketch	from Chief Services. IAW On	shore Oil & Gas Order #	2, the wellbore shall be o	covered with a	metal plate at least .25" thi	
The Bond Number on file with the B	LM is NMB000563 Letter of C	redit - Bank of Texas in	Tulsa, OK.			
The reason for abandonment is tha	t this is a Depleted Well.					
					OBBSOCI	
х.		SEE ATT	ACHED FOR			
RECLAMATION PR	OCEDURE	CONDIT	IONS OF APP	ROVAL		
ATTACHE	D	0011211			AOBBSOCD	
					enne Singer en	
 I hereby certify that the foregoing is t Peggy Diezi 	rue and correct. Name (Printed/T)	rped)		 ,	· · · · · · · · · · · · · · · · · · ·	
		Title Land F	Property Administrator		•	
Signature 1600 X	min	Date 09/01/	2009	х. •., î		
	THIS SPACE FC	R FEDERAL OR S	TATE OFFICE US			
Approved by	1		IM ENGINEER	<u> YKŲVE</u>		
Conditions of approval, if any, are attache	ed. Approval of this notice does no	t warrant or certify		Date		
that the applicant holds legal or equitable	title to those rights in the subject le	ase which would Office	Is/ Du	P 29 20(Istin Win		
entitle the applicant to conduct operations Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repr (Instructions on page 2)	U.S.C. Section 1212, make it a cri	me for any person knowingly	and will ully to make to an		gency of the United States any	
fictitious or fraudulent statements or repr	esentations as to any matter within	its jurisdiction.	CARLS	land Manai Bad fifth of	GEMENT	
(Instructions on page 2)						

٠

•

Tandem Energy Corp

Lease Name:

Texaco Federal

Well Number:

2 Service Type: PTA



Customer Representative: Mr. Rumaldo Hinojosa Service Representative: Joseph Reeves Ticket No.:

Service Date:

This information is presented in good faith, but no warranty is given by and Chief assumes no liability for advice or recommendations made concerning results to be obtained from the use of any product or service. The information presented is Chief's best estimate of the actual results that may be achieved and should be used for comparison purposes rather than absolute values. Prices quoted are estimates only and are good for 30 days from the date of issue. Actual charges may vary depending upon time, equipment, and material ultimately required to perform these services.

Chief Services

· · ·

,

1st Plug					Depths
Sacks:	5	Total Cmt	1.18	bbls	CIBP @4900'
Density:	14.8	Total cu/ft	6.60		
Yield:	1.32	Total H2O	0.75	bbls	
Water:	6.3	Hght	75 '		
2nd Plug					
Sacks:	30	Total Cmt	7.05	bbls	250-150' P&S
Density:	14.8	Total cu/ft	39.60		
Yield:	1.32	Total H2O	4.50	bbls	
Water:	6.3	Hght	100'		
3rd Plug					
					30' Top
Sacks:	10	Total Cmt	2.35	bbls	Out
Density:	14.8	Total cu/ft	13.20		
Yield:	1.32	Total H2O	1.50	bbls	
Water:	6.3	Hght	30'		

August 28, 2009 Ticket No: 0 Tandem Energy Corp 200 N. Loraine Ste. 400 Joseph Reeves Serv Sup: Midland TX State: NM 2 County: Lea Texaco Federal After Discounted **Unit Price** Quantity Unit Amount \$1,200.00 ، فرید مرجبہ میں Cement Pumping Charge \$900.00 \$1,200.00 \$1,200.00 Ea 1 E1 0 - 500', 6 hr minimum ا محمد ما ک \$675.00 Equipment Mileage Charge -----\$5.00 \$375.00 \$281.25 75 Mile E40 Equipment Mileage \$225.00 \$4.00 \$300.00 75 Mile Pick-up Mileage Charge E41

• •

Bulk Ceme	nt Delivery	n a fan fan fan fan fan fan fan fan fan			\$198.75	······································
E50	Cement Delivery	159	T/M	\$1.25	\$198.75	\$149.06
Bulk Ceme	nt and Additive Blending			مىلىرىغانىيە بىلە مەسەمەرمىيە مەسەر يىلەر يې ، - مەسەمەر مەرەمەر بىلەر مەسەر مەسەر مەسەر	\$56.25	
E60	Cement Blending	45	Sks	\$1.25	\$56.25	\$42.19
Casing Atta	achments				\$250.00	
E71	Valve and Swage	1	dol	\$250.00	\$250.00	\$187.50
Cement. A	cid and Additives	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		\$861.50	
E200	Class "C" Cement	45	Sks	\$15.00	\$675.00	\$506.25
E310	CaCl ²	85	Lbs	\$1.90	\$161.50	\$121.13
E311	Defoamer (Liquid)	1	Gal	\$25.00	\$25.00	\$18.75

Thank You for using Chief Services	Price Book Total	\$3,241.50
	Discount	\$810.38
Customer Rep.		
X	After Disc	\$2,431.13

	Post Roswell, N	nk Plaza, Suit Office Box 15 ew Mexico 882 : (505) 622-7	15 202-1515		WELL E	BORE SH	(ETCF	I	
	OPERATOR/L	EASE/WELL .	HANSON	OPERAT	ING COMPANY	Z, INC.	TEXACO	FEDERAL #2 DATE	
		UDED						DATE	,
	FIELD/POOL	Pearl		/	Queen	11!			368
	PLUG BACK I	DEPTH	4980		КВ	<u> </u>		ELEVATION	
					<u>1/4"</u>	, -			
12 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -					CE CASING: 8-5/8"	14/-!	24#	Grade	
			×		107	54/17Ph	1/1	Sac	
				Remark	te ks:				
								•	
	- the second					14	•		
	the state		Hole Size		.7-7/8"		•		
				-PROD	UCTION CAS	ING:		Grade	
	1. Sec. 1.			D 1 - 1	<u>4-1/2"</u> 4998'	Weight with	1 2	200 S	acks Cen
1				Cemer	t Top: Calcu	lated	Tem	perature Survey	/
				Remar	ks:			· · ·	
								· · · ·	
	22. Thur						•	······································	
	Lanel,							•)	
	A STATE OF A				<u> </u>				
		· ·							
	10.10				· ·		· · ·		
				TUBII Size	NG: 2-3/8"	Weight	4.5#	Grade	J-55
			•	Numb	er of Joints	159		Set at <u>495</u> .	
				Packe Bottor	n Arrangemei	nt: <u>SN (1.1</u>	10), 159	jts 2-3/8"	tbg (495
				2 2-	3/8" subs	(10.00)			
	N.L.Y.								. <u></u>
	21.22								
	1			RODS Size	27/1		_ Number	195	
			•	Gas /	nchor Set at	951'			
						an anahor	(6.00),	2 x 1-1/2" x ny rods (8.0	$\frac{12' \text{ pm}}{0}$
		PERFS:		195- 1-17	3/4" rods 4" polish	(48/5), 2. rod (16.00	-374 po)	ny 1005 (0.0	<u>~/,</u>
	Level of the				•				
	P. P. L. L.	4907' - 49 (4 SPF)	914'						
		(4 011)							
		4954' - 49 (4 SPF)	961'						
	L 11 - 1531								

Tandem Energy Corp. NM-0250: Texaco Federal #2 API: 30-025-20189 Lea County, New Mexico

- RE: Plugging and Abandonment Procedure, Conditions of Approval
 - 1. Set CIBP at 4850'. Bail at least 35' or pump at least 25 sx. (Perfs)
 - 2. Perf and squeeze 130' plug (minimum 25 sx) at 3450'. If injection rate cannot be established, set plug 50' below perfs. WOC and tag at 3320' or shallower. (BOS)
 - 3. Perf and squeeze 120' plug (minimum 25 sx) at 1990'. WOC and tag at 1870' or shallower. (TOS)
 - 4. Perf and squeeze cement plug at 257' or deeper to surface. WOC and fill in fall back in casing and/or annulus. (Casing shoe Surface)
 - 5. Clean up location.
 - 6. Install DHM.
 - 7. Submit subsequent report, with details.

See attached standard COA.

It is recommended that H2S monitoring and protection is available on site. Include accurate before and after diagrams of well for future plug and abandon NOIs.

DHW 092509

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 60th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

JDW 072709



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E Greene St

Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Interim Reclamation Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses.

Interim reclamation consists of minimizing the footprint of disturbance by reclaiming all portions of the well site not needed for production operations. The portions of the cleared well site not needed for operational and safety purposes are recontoured to a final or intermediate contour that blends with the surrounding topography as much as possible. Sufficient level area remains for setup of a workover rig and to park equipment. Topsoil is respread over areas not needed for all-weather operations. Production facilities should be clustered to maximize the opportunity for interim reclamation. In order to inspect and operate the well or complete workover operations, it may be necessary to drive, park, and operate on restored, interim vegetation within the previously disturbed area. This is generally acceptable provided damage is repaired and reclaimed following use.

To reduce final reclamation costs; maintain healthy, biologically active topsoil; and to minimize habitat, visual, and forage loss during the life of the well, all salvaged topsoil should be spread over the area of interim reclamation, rather than stockpiled.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- For wells and/or access roads not having an approved plan, or an inadequate plan for surface 2 reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). Interim reclamation is to be completed within 6 months of well completion.
- If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with interim reclamation as per approved APD or Sundry Notice. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.

It is the responsibility of the operator to monitor these locations and/or access roads until such 5. time as the operator feels that the BLM objective has been met.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979