I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Regulatory Analyst

DATE

12/11/03

Telephone No. 432 686 3689

(This space for State use)

TITLE

APPROVED BY

Conditions of approval, if any:

PETROLEUM ENGINEER

JAN 1 3 2004

State of New Mexico Form C-103 Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-025-25090 OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III STATE X 1000 Rio Brazos Rd., Aztec, NM 87410 FEE Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 LG-0272 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Aztec State 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 8. Well No. EOG Resources Inc. 3. Address of Operator 9. Pool name or Wildcat P.O. Box 2267 Midland, Texas 79702 Corbin, Abo 4. Well Location 710 Unit Letter feet from the_ North line and feet from the line Township 17S Range **NMPM** County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. X PLUG AND **ABANDONMENT** PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 12/10/03 Pump and spot 65 sx Class H from 1503' to 1300'. Pump and spot 100 sx Class H from 375' to surface. Weld on P&A marker, clean and restore location. page 2 of 2 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE. TITLE Regulatory Analyst DATE_ Type or print name Stan Wagner Telephone No. (This space for State use) JAN 1 3 2004

DATE

APPROVED BY

Conditions of approval, if any: