Form 3160-5 (August 2007)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FORM APPROVED OMB No 1004-0137 Expires: July 31, 2010


5 Lease Serial No LC-030174-B

6 If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for	such proposals.
SUBMIT IN TRIPLICATE – Other instructio	ns on page 2. 7 If Unit of CA/Agreement, Name and/or No
1 Type of Well	
Oil Well Gas Well Other	8. Well Name and No W.H. Rhodes B Federal NCT 1 #19
2. Name of Operator B C Operating, Inc.	9. API Well No. 30-025-25426
P O Box 50820	No (include area code) 10. Field and Pool or Exploratory Area Rhodes Yates Seven Rivers
	7-3030 EX. 210
4. Location of Well (Footage, Sec., T.,R.M., or Survey Description) 3300' FNL & 1980' FEL, UL J Section 26, T75S-R37E	11 Country or Parish, State Lea County, NM
12 CHECK THE APPROPRIATE BOX(ES) TO	INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION
Alter Casing	Deepen Production (Start/Resume) Water Shut-Off Fracture Treat Reclamation Well Integrity
V Sausequent Report	New Construction Recomplete Other
	Plug and Abandon Temporarily Abandon Plug Back Water Disposal
	ls, including estimated starting date of any proposed work and approximate duration thereof. If
following completion of the involved operations. If the operation results in testing has been completed. Final Abandonment Notices must be filed only determined that the site is ready for final inspection.)	ond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once y after all requirements, including reclamation, have been completed and the operator has D Field Rep witnessed test 7/15/09. Pressured casing to 560 psi for 30 mins.
	2 - 100 rep minocod test 17 10/00. Tressured dasing to 500 psi ion 30 mins.
Denied: Failure to comply with	
Conditions of Approval attached to	RECEIVED
previous sundry	OOT 1 0 0000
10-8-09	OCT 13 2009 HOBBSOCD
/s/ JD Whitlock Jr	
Last used as win 1/1997	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Tami Parker	Title Regulatory Analyst
Signature Jame Pouker	Date 09/30/2009
THIS SPACE FOR FEI	DERAL OR STATE OFFICE USE
Approved by	DISTRICT 1 SUPERVISOR Date OCT 1 9 2009
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	or certify
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for an fictitious or fraudulent statements or representations as to any matter within its jurisdictions.	y person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.

0

- b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well will be approved after successful MIT and subsequent report is submitted. Submit Plans to recomplete, produce or P&A by November 9 2009.