Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

BUREAU OF LAND MANAGEMENT

FORM APPRO	VED
· OMB No. 1004-	0137
Evniree: Inty 31	20.10

5.	Lease	Serial	No.
N	MAINA	ባይጓደጓ	٥

6 If Indian, Allottee or Tribe Name

abandoned well.	Use Form 3160-3 (A	PD) for such p	roposals.					
SOBILITIVE FIGURE OF INSTITUTIONS OF PAGE 2.					7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well Other Other				8. V	8. Well Name and No. KORCZAK FEDERAL #1			
2. Name of Operator NADEL AND GUSSMAN PERMIAN LLC					PI Well No. 025-37060-0	/-		· · · · · · · · · · · · · · · · · · ·
3a. Address		3b. Phone No. (incl.	ude area code)		Field and Pool or	Exploratory	/ Агеа	
601 N. MARIENFELD SUITE 508, MIDLAND T	K. 79701 ,	432-682-4429	•	LU	LUSK WOLFCAMP EAST			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1980 FSL, 1980 FWL, S14-T19S-R32E NMPM			i	11. Country or Parish, State LEA, NM				
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICAT	E NATURE OF	NOTICE, R	EPORT OR OT	HER DATA		
TYPE OF SUBMISSION			TYPE O	F ACTION				
Notice of Intent	Acidize Alter Casing	Deepen Fracture Tr	reat	Production	n (Start/Resume)	_	ater Shut-Off ell Integrity	
Subsequent Report	Casing Repair Change Plans	☐ New Const☐ Plug and A		Recomple	ily Abandon	Otl	her	
Final Abandonment Notice	Convert to Injection	Plug Back		Water Dis	•			
RECOMPLETE FROM THE MORR SET CIBP AT 13,000' AND CAP W PRESSURE TEST CSG AND CIBP PERFORATE THE WOLFCAMP @ ABOVE PORTABLE GROUND STE SEE ATTACHEL CONDITIONS O	OW TO THE WOLFCAMP ITH 35' OF CMT. EXISTIN TO 500 PSI 10,768-11,052' OA ACDIZ EEL FLOWBACK TANKS V FOR FAPPROVAL	IG PERFS @ 13,0: ZIE AND TEST. IF VILL BE USED FO REC OCT HOBE	NECESSARY T	THE WOLF	APP OCT S/ Chris BUREAU OF LA CARLSBAD	ROVE 1 3 2009 3 Walls	D	
14. I hereby certify that the foregoing is t KEM E. MCCREADY	rue and correct. Name (Printed		NM OPERAT	IONS MGI	₹	,	-	
Signature Kom E. W	cheady	Date	9/21/2009		KI	·		
,	THIS SPACE	FOR FEDERAL	L OR STATE	OFFIC	EUSE			
Approved by			PETROLE	JM ENG	INSEH	Date	OCT 28	200g
Conditions of approval, if any, are attache that the applicant holds legal or equitable entitle the applicant to conduct operations	itle to those rights in the subjec					prace .	,	MA
Title 19 H C C Section 1001 and Title 42	H.C. Castina 1212 and it	aziza faz azus z	la	116.114			C41 T1 '4 16	V 4

Korczak Federal #1 1980 FSL, 1980 FWL Sec 14, 198, 32E , Lea County, NM API # 30 - 025 - 37060-0

Elev: 3630', KB: 19' AG

Proposed rev 9/21/09 13-3/8", 54.5#, H-40 @ 409' 360 sx, cement circulated 50 sxs **Tubing Details** 17-1/2" hole 5-1/2" TOC @ 2390 CBL 4/06/05 9-5/8", 40#, N-80 @ 4981' 2400 sxs, cement; circ 180 sxs 12-1/4" hole DV TOOL @ 10,975' Proposed Wolfcamp Perfs 10,768-10,770 6 spf 12 holes 11,050-11,052 6 spf 12 holes CIBP@ 13,000' capped w\ 35' cmt 13,070' - 13,090' 120 holes 13,169' - 13,185' 6 spf 96 holes FIH 83.3' of dropped TCP guns
1.19' mech fh, 78' of gun assembly, .77' BP
3.73' propellant
EST TOF @ 13,283
CIBP @ 13,355' capped w\ 10' cmt
13,360'-368'; 6 spf 48 holes 5-1/2", 17 & 20#, P-110 LTC@ 0-13,640' 13,388' - 392'; 6 spf 24 holes 13,402' - 410' 6 spf 48 holes 17# 0 - 11,628' 20# 11,628' - 13,640' 1st stg 579 sxs; cir cmt off DV tool total 120 holes

PBTD @ 13,345 TD @ 13,640'

2nd stage 1645 sxs

7-7/8" hole

Korczak Fed #1 30-025-37060 Nadel and Gussman Permian LLC October 6, 2009 Conditions of Approval

- 1. Operator will be required to address the additional plug across the top of the Morrow formation at final abandonment.
- 2. Surface disturbance beyond the existing pad must have prior approval.
- 3. Closed loop system required.
- 4. Need class H cement on CIBP at 13,000'.
- 5. Operator to have H2S monitoring equipment on location, as H2S has been reported from wells in the area.
- 6. A minimum of a 3M BOP is required and must be tested prior to setting CIBP over Morrow perforations.
- 7. Contact BLM 575-393-3612 a minimum of 24 hours prior to setting CIBP.
- 8. Subsequent sundry and completion report required.

CRW 100609