Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

abandoned well. Use Form 3160-3 (APD) for such proposals.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

FORM	APP:	RO	VEI
OMB N	lo. 10	04-	013
Expires	July	31	201

5.	Lease	Serial	No.	
	C 02	0/N5/	١.	

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

N/A

SUBMIT IN TRIPLICATE Other instructions on page 2.		7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well		./			
✓ Oil Well Gas W	Vell Other			8. Well Name and No. MCA # 255	
Name of Operator ConocoPhillips Company				9. API Well No. 30-025-08049	
3a. Address 3b. Phone No. (include area code)		10 Field and Pool or Exploratory Area			
P.O. Box 51810 Midland, Tx 79710 432-688-6943		432-688-6943		Maljamar Grayburg SA	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1295 FNI. 8, 1520 FWI.		11. Country or Parish, State			
Section 20-17S-32E				Lea County, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Produ	ction (Start/Resume) Water Shut-Off	
Trouble of Intent	Alter Casing	Fracture Treat	Recla	mation Well Integrity	
Subsequent Report	Casing Repair	New Construction	Reco	nplete Other Reclamation	
	Change Plans	Plug and Abandon	Temp	oranly Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water	Disposal	
13 Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If					

the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

1. Removed any contaminated soil and caliche from the area

determined that the site is ready for final inspection)

- Put in 2' of caliche to build a barrier
- Put in 2' of fill to level and contour into surrounding areas
- Built earthern barricade at entrance to prevent vehicular traffic
- 5. Seeded all disturbed areas with BLM # 2 seed mixture using a BLM approved seeder. Job completed July 30, 2009.

RECEIVED

NOV 0 2 2009 HOBBSOCD ACCEPTED FOR RECORD

EAU OF LAND MANAGEMENT

ARLSBAD FIELD OFFICE

3 2000

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed Donna Williams Title Sr. Regulatory Specialist 09/09/2009 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by DISTRICT 1 SUPERVISOR NOV 0 2 2009 Title Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon

Title 18 U.S.C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.