

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87401
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

RECEIVED

NOV 06 2009

HOBBSOCD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-21099
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. S-91017
7. Lease Name or Unit Agreement Name: New Mexico E State
8. Well Number 4
9. OGRID Number 16696
10. Pool name or Wildcat Mescalero San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	2. Name of Operator OXY USA Inc.
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250	4. Well Location Unit Letter <u>F</u> : <u>1650</u> feet from the <u>north</u> line and <u>1650</u> feet from the <u>west</u> line Section <u>26</u> Township <u>10S</u> Range <u>32E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4311' GR	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: Run CIT ☒

Report, or Other Data
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of p or recompletion.

OXY USA Inc requests to temporarily abandon this well, this well is currently being evaluated for future use.

TD-4450' PBTD-4426' Perfs-4159-4279'

1. POOH w/ production equipment.
2. RIH & set CIBP @ 4110'
3. Notify NMOCD of casing integrity test 24hrs in advance.
4. RU pump truck, circulate well with treated water, pressure test casing to 500# for 30 min.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE David Stewart TITLE Sr. Regulatory Analyst DATE 11/5/09

Type or print name David Stewart

E-mail address: david_stewart@oxy.com
Telephone No. 432-685-5717

For State Use Only

APPROVED BY David Stewart TITLE DISTRICT 1 SUPERVISOR DATE NOV 09 2009


Conditions of Approval, if any:

OXY USA Inc.
New Mexico E State #4
API No. 30-025-21099

12-1/4" hole @ 1550'
8-5/8" csg @ 1550'
w/ 400sx-TOC-Surf-Circ

CIBP @ 4110'

PB-4426'



7-7/8" hole @ 4450'
4-1/2" csg @ 4450'
w/ 450sx-TOC-2842'-TS

Perfs @ 4159-4279'

TD-4450'