Office			State of New Mexi Minerals and Natura				Form C-10 June 19, 200
<u>District I</u> 1625 N. French	n Dr , Hobbs, NM 8824				WELL API N	NO. 🖌	
District II 1301 W. Grand	Ave Artesia NM 88	CEIVEDCO	ONSERVATION D	DIVISION	30-025-39069		······································
District III		10	20 South St. Franc	is Dr.	5. Indicate T	Type of Lease TE 🗙 FI	EE 🗆 🛩
District IV	os Rd., Aztec, NM ₩ 🖟		Santa Fe, NM 875	05		& Gas Lease N	
1220 S. St. Fra: 87505	ncis Dr , Santa É el N	BBSUCD			BO-0218		
87505	SUNDRY N	OTICES AND RE	PORTS ON WELLS		7. Lease Nar	me or Unit Agr	eement Name
	RESERVOIR USE "AI		OR TO DEEPEN OR PLUG MIT" (FORM C-101) FOR			ent G/SA Unit	1
1. Type of V	Well: 🛛 Oil Well	🔲 Gas Well 🔲	Other:		8. Well Num	nber 376	\checkmark
2. Name of Apache Corp	Operator	1			9. OGRID N 873	lumber	1
3. Address	•					ne or Wildcat	
		ulsa, OK 74136-422	24		Eunice Monur	ment; Grayburg	- San Andres
4. Well Loc		(000					. 1'
	it Letter P		from the <u>South</u>	$_$ line and $\underline{130}$		t from the <u>Eas</u>	/
Sec	tion 25		wnship 19S Rang (Show whether DR, R	ge 36E KB_RT_GR_etc	NMPM	County	Lea
		3628' GR	(Show whether DR, R	$\mathbf{K}\mathbf{D}, \mathbf{K}\mathbf{I}, \mathbf{O}\mathbf{K}, \mathbf{e}\mathbf{i}\mathbf{C}$	·/		
	12. Chee	ck Appropriate I	Box to Indicate Nat	ure of Notice,	Report or Of	ther Data	
				0.115		DEDODT	\ _
DEDEODM				SUE REMEDIAL WOF)F: IG CASING [
	REMEDIAL WORK			COMMENCE DR	-		
					-		L
	RILY ABANDON		OMPL 🗆 🛛	CASING/CEMEN	ІТ ЈОВ Г		
PULL OR A	RILY ABANDON LTER CASING E COMMINGLE		OMPL C	CASING/CEMEN	IT JOB [
PULL OR AI DOWNHOLI OTHER:	LTER CASING E COMMINGLE			OTHER: Adding F	Perfs		X
PULL OR AI DOWNHOLI OTHER: 13. Desc	LTER CASING E COMMINGLE	MULTIPLE C	s. (Clearly state all per	DTHER: Adding F tinent details, an	Perfs ad give pertinent	t dates, includi	
PULL OR AL DOWNHOLD OTHER: 13. Desc of st	LTER CASING E COMMINGLE cribe proposed or c arting any propose	MULTIPLE C		DTHER: Adding F tinent details, an	Perfs ad give pertinent	t dates, includi	
PULL OR AL DOWNHOLD OTHER: 13. Desc of st	LTER CASING E COMMINGLE	MULTIPLE C	s. (Clearly state all per	DTHER: Adding F tinent details, an	Perfs ad give pertinent	t dates, includi	
PULL OR AI DOWNHOLI OTHER: 13. Desc of st or re	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion.	MULTIPLE C	s. (Clearly state all per	DTHER: Adding F tinent details, an Completions: A	Perfs ad give pertinent ttach wellbore d	t dates, includi diagram of prop	bosed complet
PULL OR AN DOWNHOLD OTHER: 13. Desc of st or re Apache co	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion.	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G	s. (Clearly state all per E 1103. For Multiple	DTHER: Adding F tinent details, an Completions: A	Perfs ad give pertinent ttach wellbore d	t dates, includi diagram of prop	bosed complet
PULL OR AN DOWNHOLD OTHER: 13. Desc of st or re Apache co third phas	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well v e of Grayburg perfe	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows:	S. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906'	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/	Perfs nd give pertinent ttach wellbore c /2009. Apache h	t dates, includi diagram of prop nas now added	bosed completi a second and
PULL OR AN DOWNHOLD OTHER: 13. Desc of st or re Apache co	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well v e of Grayburg perf 9 Perf Grayburg 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900	s. (Clearly state all per E 1103. For Multiple	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP	Perfs nd give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz	t dates, includi diagram of prop nas now added red w/ 500 gals	a second and 15% NEFE.
PULL OR AL DOWNHOLD 0THER: 13. Desc of st or re Apache cc third phas 10/26/200 10/27/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well v e of Grayburg perf 9 Perf Grayburg 9 Release and F Set RBP @ 38	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'.	 Clearly state all per K. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase 	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP	Perfs nd give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz	t dates, includi diagram of prop nas now added red w/ 500 gals	a second and 15% NEFE.
PULL OR AL DOWNHOLD OTHER: 13. Desc of st or re Apache cc third phas 10/26/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well e of Grayburg perf 9 Perf Grayburg 9 Release and F Set RBP @ 38 9 Acidized Phas	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'. e III perfs w/ 2500 g	 Clearly state all per K. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase yals 15% NEFE. 	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3	Perfs nd give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz	t dates, includi diagram of prop nas now added red w/ 500 gals	a second and 15% NEFE.
PULL OR AL DOWNHOLD 0THER: 13. Desc of st or re Apache co third phas 10/26/200 10/27/200 10/28/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completed this well v e of Grayburg perfection 9 Perf Grayburg 9 Release and F Set RBP @ 38 9 Acidized Phas 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'. e III perfs w/ 2500 @ POOH RBP @ 3868	 Clearly state all per K. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase 	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 ping to 3993'.	Perfs ad give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AL DOWNHOLD 0THER: 13. Desc of st or re Apache co third phas 10/26/200 10/27/200 10/28/200 10/29/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completed this well v e of Grayburg perfection 9 Perf Grayburg 9 Release and F Set RBP @ 38 9 Acidized Phas 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'. e III perfs w/ 2500 @ POOH RBP @ 3868	 c. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase yals 15% NEFE. '. RIH w/ production tul 	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 ping to 3993'.	Perfs ad give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AL DOWNHOLD 0THER: 13. Desc of st or re Apache co third phas 10/26/200 10/27/200 10/28/200 10/29/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completed this well v e of Grayburg perfection 9 Perf Grayburg 9 Release and F Set RBP @ 38 9 Acidized Phas 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'. e III perfs w/ 2500 @ POOH RBP @ 3868	 c. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase yals 15% NEFE. '. RIH w/ production tul 	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 ping to 3993'.	Perfs ad give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AL DOWNHOLD 0THER: 13. Desc of st or re Apache co third phas 10/26/200 10/27/200 10/28/200 10/29/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completed this well v e of Grayburg perfection 9 Perf Grayburg 9 Release and F Set RBP @ 38 9 Acidized Phas 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'. e III perfs w/ 2500 @ POOH RBP @ 3868	 c. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase yals 15% NEFE. '. RIH w/ production tul 	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 ping to 3993'.	Perfs ad give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AL DOWNHOLD 0THER: 13. Desc of st or re Apache co third phas 10/26/200 10/27/200 10/28/200 10/29/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completed this well v e of Grayburg perfection 9 Perf Grayburg 9 Release and F Set RBP @ 38 9 Acidized Phas 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'. e III perfs w/ 2500 @ POOH RBP @ 3868	 c. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase yals 15% NEFE. '. RIH w/ production tul 	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP a III @ 3750-58, 3 bing to 3993'. production Grayb	Perfs ad give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache co third phas 10/26/200 10/27/200 10/29/200 10/29/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well w e of Grayburg perfection 9 Perf Grayburg 9 Release and F 9 Release and F 9 Release and F 9 Release and F 9 RIH w/ pump a	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3900 368'. e III perfs w/ 2500 @ POOH RBP @ 3868	s. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase jals 15% NEFE. '. RIH w/ production tul umping unit. Place on p	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP a III @ 3750-58, 3 bing to 3993'. production Grayb	Perfs ad give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache cc third phas 10/26/200 10/27/200 10/28/200 10/29/200 10/30/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well v e of Grayburg perf 9 Perf Grayburg 19 Release and F 9 Release and F 9 Release and F 9 Release and F 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3800 368'. POOH RBP @ 3868 and rods Set 456 p	s. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase jals 15% NEFE. '. RIH w/ production tul umping unit. Place on p Rig Release Date	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 bing to 3993'. broduction Grayb	Perfs Id give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383 burg Phase I, II, a	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache cc third phas 10/26/200 10/27/200 10/28/200 10/29/200 10/30/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well v e of Grayburg perf 9 Perf Grayburg 19 Release and F 9 Release and F 9 Release and F 9 Release and F 9 Release and F	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3800 368'. POOH RBP @ 3868 and rods Set 456 p	s. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase jals 15% NEFE. '. RIH w/ production tul umping unit. Place on p	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 bing to 3993'. broduction Grayb	Perfs Id give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383 burg Phase I, II, a	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache cc third phas 10/26/200 10/27/200 10/28/200 10/29/200 10/30/200	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well w e of Grayburg perfs 9 Perf Grayburg 9 Release and F 9 Release and F 9 Release and F 9 RIH w/ pump a 09/14/2009	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3800 368'. e III perfs w/ 2500 g POOH RBP @ 3868 and rods Set 456 p	s. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase jals 15% NEFE. '. RIH w/ production tul umping unit. Place on p Rig Release Date	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 bing to 3993'. broduction Grayb	Perfs Id give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383 burg Phase I, II, a	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache cc third phas 10/26/200 10/27/200 10/28/200 10/29/200 10/30/200 Spud Date:	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well w e of Grayburg perfs 9 Perf Grayburg 9 Release and F 9 Release and F 9 Release and F 9 RIH w/ pump a 09/14/2009	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3800 368'. e III perfs w/ 2500 g POOH RBP @ 3868 and rods Set 456 p	Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase jals 15% NEFE. '. RIH w/ production tul umping unit. Place on p Rig Release Date	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 bing to 3993'. broduction Grayb : 09/20/2009 of my knowledg	Perfs Id give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383 burg Phase I, II, a	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9 and III.	a second and 15% NEFE. 4 holes.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache ca third phas 10/26/200 10/27/200 10/27/200 10/29/200 10/30/200 Spud Date:	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well w e of Grayburg perfs 9 Perf Grayburg 9 Release and F 9 Release and F 9 Release and F 9 RIH w/ pump a 09/14/2009	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3800 368'. e III perfs w/ 2500 g POOH RBP @ 3868 and rods Set 456 p	s. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase jals 15% NEFE. '. RIH w/ production tul umping unit. Place on p Rig Release Date	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 bing to 3993'. broduction Grayb : 09/20/2009 of my knowledg	Perfs Id give pertinent ttach wellbore d /2009. Apache h @ 3900'. Acidiz 3788-3804, 383 burg Phase I, II, a	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9	a second and 15% NEFE. 4 holes.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache ca third phas 10/26/200 10/27/200 10/27/200 10/29/200 10/30/200 Spud Date:	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well w e of Grayburg perfs 9 Perf Grayburg 9 Release and F 9 Release and F 9 Release and F 9 Release and F 9 RIH w/ pump a 09/14/2009	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3800 368'. e III perfs w/ 2500 g POOH RBP @ 3868 and rods Set 456 p	Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase jals 15% NEFE. '. RIH w/ production tul umping unit. Place on p Rig Release Date	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 bing to 3993'. broduction Grayb : 09/20/2009 of my knowledg	Perfs ad give pertinent ttach wellbore of /2009. Apache h @ 3900'. Acidiz 3788-3804, 383 burg Phase I, II, a ge and belief.	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9 and III.	a second and 15% NEFE. 4 holes.
PULL OR AI DOWNHOLI 13. Desc of st or re Apache ca third phas 10/26/200 10/27/200 10/27/200 10/29/200 10/30/200 Spud Date:	LTER CASING E COMMINGLE cribe proposed or c arting any propose completion. completed this well w e of Grayburg perfs 9 Perf Grayburg 9 Release and F 9 Release and F 9 Release and F 9 Release and F 9 RIH w/ pump a 09/14/2009	MULTIPLE C ompleted operation d work). SEE RUL with one phase of G s as follows: Phase II @ 3874-7 POOH RBP @ 3800 368'. e III perfs w/ 2500 g POOH RBP @ 3868 and rods Set 456 p	s. (Clearly state all per E 1103. For Multiple rayburg perfs fr/ 3906' 7, 3881-83', 2 SPF, 14 '. Perf Grayburg Phase gals 15% NEFE. '. RIH w/ production tul umping unit. Place on p Rig Release Date d complete to the best	DTHER: Adding F tinent details, an Completions: A - 3986' on 10/03/ holes. Set RBP e III @ 3750-58, 3 bing to 3993'. broduction Grayb : 09/20/2009 of my knowledg	Perfs Id give pertinent ttach wellbore d (2009. Apache h @ 3900'. Acidiz 3788-3804, 383 burg Phase I, II, i ge and belief.	t dates, includi diagram of prop nas now added eed w/ 500 gals 1-51', 2 SPF, 9 and III.	5/2009