Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR OCD-HOBBS BUREAU OF LAND MANAGEMENT

OMB No. 1004-0137 Expires: July 31, 2010

6. If Indian, Allottee or Tribe Name

FORM APPROVED

5. Lease Serial No. LC4-032650-B

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals

apandoned well.	USE FUIII 3100-3 (AF	D) lui sucii propusai	13.		
SUBMI	T IN TRIPLICATE – Other in	7. If Unit of CA/Agree NMNM87877X	ment, Name and/or No.		
I. Type of Well		TAIVITAIVIOTOTTX			
Oil Well Gas W	/ell	8. Well Name and No. SOUTH JUSTIS U	NIT F-194		
2. Name of Operator LEGACY RESERVES OPERATING LP 9. API Well No. 30-025-32409					
Ba. Address P.O. BOX 10848	3	ode) 10. Field and Pool or E			
MIDLAND, TX 79702		Justis / Re	linebry Tubb		
. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State					
UNIT LETTER B, SEC 24, 25S, 37E, 1100' FNL & 1350' FEL Lea Co.					
12. CHEC	CK THE APPROPRIATE BOX	(ES) TO INDICATE NATUR	E OF NOTICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION	SUBMISSION TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
	Casing Repair	New Construction	Recomplete	✓ Other MECHANICAL	
✓ Subsequent Report	Change Plans	Plug and Abandon	Temporarily Abandon	INTEGRITY TEST	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

9/30/09 - RU, unflange wellhead, release pkr. POOH w/ tbg & pkr. RU tester to test in hole w/ pkr. NDBOP. Circulate w/ pkr fluid. Set pkr and pressure test for 30 min., held OK. RDMO.

10/19/09 - Ran MIT, tested to 495#, held OK. Witnessed by Mark Whitaker w/ OCD. Chart attached.

RECEIVED

NOV 12 2009 HOBBSOCD

ACCEPTED FOR RECORD					
	NOV 9 2009				
	/s/ Chris Walls				
BL	REAU OF LAND MANAGEMEN CARLSBAD FIELD OFFICE	VT			

	CARLSBAD FIELD OFFICE
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Berry Johnson	Title Production Superintendent
Signature Benz Johnson	Date 10/29/2009
THIS SPACE FOR FED	DERAL OR STATE OFFICE USE
Approved by	DISTRICT & SUPERVISOR NOV 1 6 2009
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	or certify
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any	person knowingly and willfully to make to any department or agency of the United States any fals

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

