, Submit 3 Copies To Appropriate District St	ate of New Mexico	Form C-103
Office Enorgy Mi	nerals and Natural Resources	June 19, 2008
		WELL API NO. 30-005-10588
	SERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Big Prozes Rd Artee NIM 97 NUV 1 6 7009 1220	South St. Francis Dr.	STATE FEE X
	nta Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr., Santa Fe, NOBBSOCD 87505		
SUNDRY NOTICES AND REPO	RTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR	TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMI" PROPOSALS )	1" (FORM C-101) FOR SUCH	CATO SAN ANDRES UNIT
1. Type of Well: Oil Well Gas Well Other CONVERT TO INJECTOR		8. Well Number 85
2. Name of Operator		9. OGRID Number 248802
CANO PETRO OF NEW MEXICO, INC. 3. Address of Operator		10. Pool name or Wildcat
801 CHERRY STR, UNIT 25 SUITE 320	0 FT WORTH TX 76102	CATO; SAN ANDRES
4. Well Location		
	om the NORTH line and	<sup>.980</sup> feet from the <sup>EAST</sup> line
	ship <sup>08S</sup> Range <sup>30E</sup>	NMPM <sup>27</sup> County CHAVES
	Show whether DR, RKB, RT, GR, etc.,	
and the second second	4136 RDB	
12. Check Appropriate Box	x to Indicate Nature of Notice,	Report or Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CAS		
TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       P AND A         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT JOB		
DOWNHOLE COMMINGLE		
OTHER.		t to water injection well
OTHER. 13. Describe proposed or completed operations.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER. 13. Describe proposed or completed operations.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER. 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated date
OTHER. 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/20/09 MIRU pulling unit.	(Clearly state all pertinent details, and 103. For Multiple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion R- 9D29-A
OTHER. 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/20/09 MIRU pulling unit. 10/21/09 TIH w/ 3-3/4" cone 1	(Clearly state all pertinent details, and 1103. For Multiple Completions: At bit and cleaned out to TE	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion R - QD 2Q - A (3545')
OTHER. 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 10/20/09 MIRU pulling unit. 10/21/09 TIH w/ 3-3/4" cone I 10/23/09 Ran 3-1/2" 9.3# J-5	(Clearly state all pertinent details, and 103. For Multiple Completions: At bit and cleaned out to TE 5 flush jt liner from sur	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}_{-}$ QDQQ- $\mathcal{A}_{-}$ (3545') face to TD.
OTHER.13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.10/20/09MIRU pulling unit.10/21/09TIH w/ 3-3/4" cone I10/23/09Ran 3-1/2" 9.3# J-510/23/09Cemented w/ 100 sx	(Clearly state all pertinent details, and 1103. For Multiple Completions: At bit and cleaned out to TE 5 flush jt liner from sur 50/50 Poz and 200 sx clas	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}_{-}$ QDQQ- $\mathcal{A}_{-}$ (3545') face to TD.
OTHER.13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.10/20/09MIRU pulling unit.10/21/09TIH w/ 3-3/4" cone10/23/09Ran 3-1/2" 9.3# J-510/23/09Cemented w/ 100 sx10/27/09Perforated San Andre	(Clearly state all pertinent details, and 1103. For Multiple Completions: At bit and cleaned out to TE 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601'@2 spf	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}_{-}$ <b>QDQQ-</b> $\mathcal{A}$ (3545') face to TD. s C. WOC.
OTHER.13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.10/20/09MIRU pulling unit.10/21/09TIH w/ 3-3/4" cone I10/23/09Ran 3-1/2" 9.3# J-510/23/09Cemented w/ 100 sx10/27/09Perforated San Andres10/28/09Acidized San Andres	(Clearly state all pertinent details, and 1103. For Multiple Completions: At bit and cleaned out to TE 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601'@2 spf w/ 6,000 gal 28% HCl@7	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}_{-}$ <b>QDQQ-A</b> (3545') face to TD. s C. WOC. BPM
<ul> <li>OTHER.</li> <li>13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.</li> <li>10/20/09 MIRU pulling unit.</li> <li>10/21/09 TIH w/ 3-3/4" cone I 10/23/09 Ran 3-1/2" 9.3# J-5.</li> <li>10/23/09 Cemented w/ 100 sx 10/27/09 Perforated San Andres 10/28/09 Acidized San Andres 10/30/09 RIH w/ 2-1/16" seal</li> </ul>	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{AQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded
OTHER.13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.10/20/09MIRU pulling unit.10/21/09TIH w/ 3-3/4" cone I10/23/09Ran 3-1/2" 9.3# J-510/23/09Cemented w/ 100 sx10/27/09Perforated San Andres10/28/09Acidized San Andres10/30/09RIH w/ 2-1/16" seal backside w/ fresh with	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601'@2 spf w/ 6,000 gal 28% HCl@7 tite tubing and packer. ater and performed MIT.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{AQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded
OTHER.13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.10/20/09MIRU pulling unit.10/21/09TIH w/ 3-3/4" cone I10/23/09Ran 3-1/2" 9.3# J-510/23/09Cemented w/ 100 sx10/27/09Perforated San Andres10/28/09Acidized San Andres10/30/09RIH w/ 2-1/16" sealbackside w/ fresh wate	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{AQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded
OTHER.13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.10/20/09MIRU pulling unit.10/21/09TIH w/ 3-3/4" cone I10/23/09Ran 3-1/2" 9.3# J-510/23/09Cemented w/ 100 sx10/27/09Perforated San Andres10/28/09Acidized San Andres10/30/09RIH w/ 2-1/16" seal backside w/ fresh with	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601'@2 spf w/ 6,000 gal 28% HCl@7 tite tubing and packer. ater and performed MIT.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{AQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5         10/23/09       Cemented w/ 100 sx         10/23/09       Cemented San Andres         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w         10/30/09       Started water inject	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{AQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded
OTHER.13. Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion.10/20/09MIRU pulling unit.10/21/09TIH w/ 3-3/4" cone I10/23/09Ran 3-1/2" 9.3# J-510/23/09Cemented w/ 100 sx10/27/09Perforated San Andres10/28/09Acidized San Andres10/30/09RIH w/ 2-1/16" seal backside w/ fresh with	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601'@2 spf w/ 6,000 gal 28% HCl@7 tite tubing and packer. ater and performed MIT.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{AQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5         10/23/09       Cemented w/ 100 sx         10/23/09       Cemented San Andres         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w         10/30/09       Started water inject	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{AQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5         10/23/09       Cemented w/ 100 sx         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh water       10/30/09         Spud Date:       12/29/66	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{XQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed.
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5         10/23/09       Cemented w/ 100 sx         10/23/09       Cemented San Andres         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w         10/30/09       Started water inject	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{XQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed.
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone 1         10/23/09       Ran 3-1/2" 9.3# J-5.         10/23/09       Cemented w/ 100 sx         10/23/09       Cemented w/ 100 sx         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w       10/30/09         Spud Date:       12/29/66	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}_{-}$ <b>QD</b> $\mathcal{Q}_{-}$ <b>A</b> (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed.
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5         10/23/09       Cemented w/ 100 sx         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh water       10/30/09         Spud Date:       12/29/66	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{XQ}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed.
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5         10/23/09       Remented w/ 100 sx         10/23/09       Cemented w/ 100 sx         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w       10/30/09         Spud Date:       12/29/66	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67 complete to the best of my knowledg 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{QP}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed. e and belief. DATE <u>11/03/09</u>
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5.         10/23/09       Cemented w/ 100 sx         10/23/09       Cemented w/ 100 sx         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w       10/30/09         Spud Date:       12/29/66         Ileneby certify that the information above is true and other         SIGNATURE         MAWLMAUZ,         Type or printhame       Colllin Strawn	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}_{-}$ <b>QD</b> $\mathcal{Q}_{-}$ <b>A</b> (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed.
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE is         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone if         10/23/09       Ran 3-1/2" 9.3# J-5         10/23/09       Remented w/ 100 sx         10/23/09       Cemented w/ 100 sx         10/23/09       Cemented w/ 100 sx         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w       backside w/ fresh w         10/30/09       Started water inject         Spud Date:       12/29/66         I hereby certify that the information above is true and of         SIGNATURE       MAMAMAUZ         Type or printhame       Collin Strawn         For State Use Only       Man M.M.	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67 complete to the best of my knowledg TITLEEngineer E-mail address:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}$ - $\mathcal{QD}\mathcal{R}$ - $\mathcal{A}$ (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed. e and belief. DATE <u>11/03/09</u> PHONE: <u>817-698-0900</u>
OTHER.         13. Describe proposed or completed operations.         of starting any proposed work). SEE RULE         or recompletion.         10/20/09       MIRU pulling unit.         10/21/09       TIH w/ 3-3/4" cone I         10/23/09       Ran 3-1/2" 9.3# J-5.         10/23/09       Cemented w/ 100 sx         10/23/09       Cemented w/ 100 sx         10/27/09       Perforated San Andres         10/28/09       Acidized San Andres         10/30/09       RIH w/ 2-1/16" seal         backside w/ fresh w       10/30/09         Spud Date:       12/29/66         Ileneby certify that the information above is true and other         SIGNATURE         MAWLMAUZ,         Type or printhame       Colllin Strawn	(Clearly state all pertinent details, and 1103. For Multiple Completions: At 5 flush jt liner from sur 50/50 Poz and 200 sx clas es: 3553-3601' @ 2 spf w/ 6,000 gal 28% HCl @ 7 tite tubing and packer. ater and performed MIT. tion into San Andres. Rig Release Date: 1/04/67 complete to the best of my knowledg 	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion $\mathcal{R}_{-}$ <b>QD</b> $\mathcal{R}_{-}$ <b>A</b> (3545') face to TD. s C. WOC. BPM Set packer @ 3477'. Loaded MIT passed. e and belief. DATE <u>11/03/09</u> PHONE: <u>817-698-0900</u>

¢

