

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD Hobbs  
**RECEIVED**

DEC 07 2009

HOBBSOCD

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**

**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals**

5. Lease Serial No

LC-02791 A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

North El Mar Unit  
NM 70994X

8. Well Name and No

North El Mar Unit #20

9. API Well No

30 025 08431

10. Field and Pool, or Exploratory Area

El Mar (Delaware)

11. County or Parish, State

Lea County, N.M.

**SUBMIT IN TRIPLICATE - Other Instructions on reverse side**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Sahara Operating Company

3a. Address

P.O. Box 4130, Midland, TX 79704

3b. Phone No (include area code)

432/697-0967

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 660' FWL, Sec 30, T26S, R33E, NMPM  
Unit Letter "L"

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**

**TYPE OF ACTION**

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treatment

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be file within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Wellbore has been P&A as follows:

11-10-2009 MIRU Mayo-Marrs. ND WH, NU BOP. POH w/tbg. RIH and tag CIBP @ 4610'. Circ hole w/plugging mud. Spot 25 sx @ 4610'. PUH and spot 25 sx @ 2683'. POH, SDON

11-11-2009 RIH and Perf 1120', POH, RIH w/pkr and squeeze 35 sx. POH. WOC, tag 1030'. RIH and Perf 403', POH, RIH & squeeze 35 sx. WOC, tag 242'. POH. RIH & Perf 60', fill to surface in/out w/15 sx. SDON.

11-12-2009 Rig down. Dug out wellhead and cut off. Installed dry hole marker. Clean loc, move out

Wellbore P&A. Site restoration pending. All operations conducted with steel pits.

**ACCEPTED FOR RECORD**

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Robert McAlpine

Title

President

Signature

Date

11/18/2009

DEC 3 2009

BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

DEC 08 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office