

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED
OMB NO 1004-0135
Expires January 31, 2004

RECEIVED

DEC 09 2009

SUDDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1 Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No NM-0141013
2 Name of Operator CIMAREX ENERGY CO. OF COLORADO ATTN: ZENO FARRIS		6 If Indian, Allottee or Tribe Name
3a Address 600 N. MARIENFELD, SUITE 600, MIDLAND, TX 79701	3b. Phone No. (include area code) 432.571.7800	7 If Unit or CA/Agreement, Name and/or No NM-72572
4 Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT LETTER B 660' FNL & 2,030' FEL SEC. 19, T-19S, R-34E		8 Well Name and No PENNZOIL RIDGE COM #1
		9 API Well No 30-025-27070
		10 Field and Pool, or Exploratory Area QUAIL RIDGE; MORROW
		11. County or Parish, State LEA NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

08/04/09: CHEMICALLY CUT 2-7/8" TBG. ABOVE PERMANENT PKR. @ 12,980' (PER PATRICIA W/ BLM); POOH W/ TBG.

08/06/09: SET 5-1/2" CIBP @ 12,980'; CIRC. WELL W/ PXA MUD.

11/09/09: MIX X PUMP A 60 SX. CMT. PLUG @ 12,980'-12,500' (CALC).

11/10/09: PERF. SQZ. HOLES IN 5-1/2" CSG. @ 11,117'-18'; PRES. UP ON SQZ. PERFS. TO 750# X HELD PRES.; MIX X PUMP A 35 SX. CMT. PLUG @ 11,180'; WOC X DID NOT TAG CMT. PLUG.

11/11/09: PRES. UP ON SQZ. PERFS. @ 11,117'-18' TO 1,000# X COULD NOT PUMP INTO PERFS.; MIX X PUMP A 35 SX. CMT. PLUG @ 11,180'; WOC X TAG TOP OF CMT. PLUG @ 10,940'; PERF. SQZ. HOLES @ 8,050'.

11/12/09: PRES. UP ON SQZ. PERFS. TO 900# X COULD NOT PUMP INTO PERFS.; MIX X PUMP A 50 SX. CMT. PLUG @ 8,100'; WOC X TAG TOP OF CMT. PLUG @ 7,733'; PERF. SQZ. HOLES @ 6,595'; COULD NOT EST. RATE.

11/13/09: MIX X PUMP A 50 SX. CMT. PLUG @ 6,658'; WOC X TAG TOP OF CMT. PLUG @ 6,500'; MIX X PUMP A 25 SX. CMT. PLUG @ 6,500'; WOC X TAG TOP OF CMT. PLUG @ 6,391'; CUT & PULL 5-1/2" CSG. @ +/-5,300'.

11/18/09: MIX & PUMP A 100 SX. CMT. PLUG @ 5,370'; WOC & TAG CMT. PLUG @ 4,880'; MIX & PUMP A 50 SX. CMT. PLUG @ 3,443'; WOC & TAG CMT. PLUG @ 3,290'; MIX X PUMP A 40 SX. CMT. PLUG @ 1,675'.

11/19/09: DID NOT TAG CMT. PLUG; MIX X PUMP A 40 SX. CMT. PLUG @ 1,675'; WOC X TAG CMT. PLUG @ 1,421'.

11/20/09: MIX & PUMP A 40 SX. CMT. PLUG @ 455'; WOC & TAG CMT. PLUG @ 330'; MIX X PUMP A 25 SX. CMT. PLUG @ 63'-3'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASINGS X INSTALL DRY

14 I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

DAVID A. EYLER

WELL PLUGGED AND ABANDONED 11/20/09.

Title

AGENT

Date 11/20/09

ACCEPTED FOR RECORD

Accepted as to plugging of this well. FOR FEDERAL OR STATE OFFICE USE

Approved by

Liability under bond is retained until
Surface restoration is completed.

DISTRICT 1 SUPERVISOR

Title
Office

DEC 5 2009

DEC 10 2009

BUREAU OF LAND MANAGEMENT

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.