

Submit 1 Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88202
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

RECEIVED CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
DEC 07 2009
HOBBSOCD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-28145
1. Type of Well: X Oil Well Gas Well Other		5. Indicate Type of Lease STATE X FEE <input type="checkbox"/>
2. Name of Operator CrownQuest Operating, LLC		6. State Oil & Gas Lease No. 543950
3. Address of Operator 303 Veterans Airpark Lane, STE 5100, PO Box 53310, Midland, TX 79710		7. Lease Name or Unit Agreement Name New Mexico "AT" State
4. Well Location Unit Letter K 1650 feet from the South line and 2305 feet from the west line Section 15 Township 14S Range 33E NMPM County Lea		8. Well Number 10
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4212' GR		9. OGRID Number 213190
		10. Pool name or Wildcat Saunders Permo Upper Penn

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: X Location is ready for OCD inspection after P&A	

- X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- X All other environmental concerns have been addressed as per OCD rules.
- X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- X I hereby certify that the information above is true and complete to the best of my knowledge and belief.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Don Rogers TITLE Manager of Special Projects DATE 12/3/09
Type or print name Don Rogers E-mail address: drogers@crowquest.com PHONE: 432 818 0300
For State Use Only
APPROVED BY: Maureen Brown TITLE Compliance Officer DATE 12/22/2009
Conditions of Approval (if any):