Submit 3 Copies To Appropriate District Office District I	,	Form C-103 June 19, 2008
District I 1625 N French Dr., Hobbs, NM 87240	WELL API NO.	
District II IANO HE CONTOURNE A TRIONI TOTALICANI	30-025-06278 5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District III Santa Fe, NM 87505	· · · · · · · · · · · · · · · · · · ·	FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease	No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit A A B Reeves	greement Name:
1. Type of Well: Oil Well Gas Well X Other	8. Well Number 2	/
2. Name of Operator	9. OGRID Number	_
XTO Energy, Inc.	005380 10. Pool name or Wildca	t
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701	Eumont: Yates-7 Rvrs	
4. Well Location		/
Unit Letter E: 1980' feet from the North line and	660' feet from the_	West line
Section 29 Township 20S Range 37E	NMPM Cou	inty Lea
11. Elevation (Show whether DR, RKB, RT, GR, et	c.)	,
10 Cl 1 A D 4 I I 4 N 4 CN I I 1 CN I I I I I I I I I I I I I I I I I I	David an Other Data	· · · · · · · · · · · · · · · · · · ·
12. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data	
NOTICE OF INTENTION TO	SEQUENT REPORT	r OE:
_		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	<u> </u>	ERING CASING
TEMPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLI	<u>=</u>	ND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT J	OB L	
DOWNHOLE COMMINGLE		
<u></u>		·
OTHER: OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion.	n wellbore diagram of prop	osed completion
1. MIRU PU. ND WH. NU BOP. Unset Baker 7" Lok-Set Pkr. POOH & LD pkr.	*65x(35'	
2. MI Wireline Co. RIH w/7" CIBP. Wireline set CIBP 3225'.		•
3. RIH & dump 3 sks Class "C" cmt w/2% CaCl on top of CIBP. RDMO. MI fluid. Notify NMOCD of intent to perform MIT.	pmp trk. Circulate IC	A clean w/pkr
4. Perform MIT to 500 psig for 30 mins. MO pmp trk. ND BOP. NU WH. RE		
Condition of Appr office 24 hours p	oval: Notify OCD Hobbs rior to running MIT Test	& Chart
Spud Date: Rig Release Date:		
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief.	
SIGNATURE Kush Ward TITLE Regulato	ry Analyst DATI	
kristy ward@xto		01/05/10
m to Mandalus Mandalus T 11 11	energy.com	
Type or print name Kristy Ward E-mail address:	penergy.com PHO1	01/05/10 NE 432-620-6740
	penergy.com PHOD Le Officer DATE	NE 432-620-6740