

RECEIVED  
JAN 05 2010  
HOBBSOCD

OCD-HOBBS

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

## 1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

## 2. Name of Operator

OXY USA Inc.

16696

## 3a. Address

P.O. Box 50250, Midland, TX 79710-0250

## 3b. Phone No. (include area code)

432-685-5717

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

657 FNL 654 FWL NWNW(D) Sec 3 T24S R37E

## 5. Lease Serial No.

LC032339A

## 6. If Indian, Allottee or Tribe Name

## 7. If Unit or CA/Agreement, Name and/or No.

## 8. Well Name and No.

G.H. Mattix

#4

Federal

## 9. API Well No.

30-025-10985

## 10. Field and Pool, or Exploratory Area

Langlie Mattix 7R Qn

## 11. County or Parish, State

Lea

NM

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

## TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

12/14/09 MIRU. POOH W/ ROD & PUMP, NDWH, NU BOP, POOH W/ TBG  
12/15/09 RIH & SET CIBP @ 3455', CIRC W/ 10# MLF, SPOT 30SX CMT ON CIBP, CALC TOC @ 3285'  
PUH @ 2917', LOAD HOLE, SPOT 35SX CMT, CALC TOC @ 2719'  
PUH @ 2536', LOAD HOLE, SPOT 35SX CMT, POOH, WOC  
12/16/09 RIH & TAG CMT @ 2323', PUH TO 1363', SPOT 30SX CMT W/ 2% CACL2, POOH, WOC.  
RIH, TAG CMT @ 1204', PUH TO 380', CIRC 65SX CMT, CIRC TO SURFACE, POOH  
NDBOP, TOP CSG W/ CMT, RDMO, WELL P&A'd.

Accepted as to plugging of the well bore.  
Liability under bond is retained until  
Surface restoration is completed.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

David Stewart

## Title

Sr. Regulatory Analyst

## Date

12/21/09

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

## Approved by

## Title

## Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

DEC 29 2009

BUREAU OF LAND MANAGEMENT

CARLSBAD FIELD OFFICE

JAN 06 2010