Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONGERNATION DIVIGION		WELL API NO. 30-025-04910	
1301 W. Grand Avenue, Artesia, NM 88210 District III	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE 🚺 FEE 🗆	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:			7. Lease Name or Unit Agreement Name: W.A. Ramsay NCT-A	
Oil Well Gas Well Other			•	
2. Name of Operator Chevron USA Inc			8. Well No. 23	
3. Address of Operator 15 Smith Rd, Midland, TX, 79705			9. Pool name or Wildcat Eumont-Yates-7 Rvrs-Queen	
4. Well Location				
Unit Letter   : 19	980 feet from the Sout	h line and	660 feet fro	om the East line
Section 34	Township 21-S R	ange 36-E	<sub>NMPM</sub> Lea	County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTE	ENTION TO: LUG AND ABANDON []	SUB:	SEQUENT RE	EPORT OF: ALTERING CASING
TEMPORARILY ABANDON C	HANGE PLANS	COMMENCE DRI	LLING OPNS.	PLUG AND
	OMPLETION	CASING TEST AN	ND	ABANDONMENT 🖳
OTHER:		OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1. Set 5 1/2" CIBP at 3680, spot 25sx, plug from 3680-3500 (Queen) Tag at 3460. 2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL. 3. Spot 25sx, plug from 3200-3000 (B-Salt, Yates). 4. Spot 25sx, plug from 1600-1400 (T-Salt) Tag at 1321. 5. Circ cmt from 350-Surf w/45sx (8 5/8 Shoe, Surf) Tag at Surf. 6. Install dry hole marker 1-16-04.				
surface restoration	gging of the Well Bore. I is retained until is completed.		(,	1234 SOUND SOLVE STANDING SOLVES SOLV
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE	TITLE	Manager/Suns	set	DATE_1/16/04
Type or print name Jimmy Bagle				phone No. (432) 561-8600
(This space for State use)  APPPROVED BY	). Wink TITLE	FIELD REPRESENTA	ative II/Staff M	MANAGER AN 2 2 2004