Form 3160-5 (August 1999)

12/17/2009

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FEU 1 9 2010 OBBSOCD FORM APPROVED OMB No 1004-0135 Expires November 30,2000

5 Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

LC-069515
6. If Indian, Allottee or Tribe Name

ile	SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.						
				and the first	North E	l Mar Unit		
1.	Type of Well				NM 70994	X		
	Oil Well	Gas Well 🔲 Other	8. Well Name ar	id No.				
2.	Name of Operator		North El M 9. API Well No.	far Unit #7				
Sahara Operating Company						_/		
3a.	Address	ass 3b. Phone No. (include area code)			30 025 08286 V			
i	P.O. Box 4130, Midland	I, TX 79704	432/697-0967		10. Field and Pool, or Exploratory Area			
4	Location of Well (Footage,		El Mar (Delaware) 🖊					
	660' FNL & 1980' FV		11. County or Pa	rish, State				
	Unit Letter "C"	, , ,	<i>,</i>		Lea Coun	ity, N.M.		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION			TYPE OF ACTION					
		Acıdize	☐ Deepen	Production	(Start/Resume)	☐ Water Shut-Off		
Ш	Notice of Intent	☐ Alter Casing	Fracture Treatment	Reclamation	on	☐ Well Integrity		
\boxtimes	Subsequent Report	Casing Repair	☐ New Construction	Recomplet	te	Other		
		Change Plans	Plug and Abandon	Temporari	ly Abandon			
	Final Abandonment Notice	Convert to Injection	☐ Plug Back	Water Disp	'ater Disposal			
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be file within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)								
Well has been P&A as follows:								
12/1	12/16/2009 MIRU Mayo Marrs. POH w/rods, ND WH, NU BOP. TIH and tag Retainer @ 3770'. Circ							

hole w/ plugging mud, POH. RIH & Perf 920', sqz 35 sx, POH WOC, SDON.

Installed dry hole marker and cleaned up location. Moved out.

RIH & tag @ 745'. POH & Perf 400', sqz 35 sx. POH, WOC. TIH and Tag @ 221'.

POH. TIH & Perf @ 60', circulate 15 sx. Rig down, dug out and cut off wellhead.

Well P&A as to wellbore. Surface restoration pending. All operations conducted using steel pits.

Accepted as to plugging of the well bore Liability under bond is retained until Surface restoration is completed.

14. I hereby certi	tify that the foregoing is true and correct			
Name (Printe	:d/Typed)	İ		
]	Robert McAlpine	Title	President	
Signature	ANA/	Date	12/21/2009	ACCEPTED FOR RECORD
	THIS SPACE FOR FEDERAL	OR STATE	OFFICE USE	VEHSTAFF MANAGE
Approved by	EG 2/23/1	O Title	NEYNESEIGH / S	Date JAN 2 8 2010
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify the applicant holds legal or equitable title to those rights in the subject lease which would entitle applicant to conduct operations thereon				SHOTAH OFHAND
Title 18 U.S C Sect false, fictitious or fra	tion 1001 and Title 43 U S C Section 1212, make it a crime for any person audulent statements or representations as to any matter within its jurisdiction.	n knowingly an	d willfully to make to any	department of agency of the United States any CF