Submit 3 Copies To Appropriate District	State of New Mex	ico		Form C-103
Office District I	Energy, Minerals and Natura	al Resources		March 4, 2004
1625 N. French Dr., Hobbs, NM 88240		•	ELL API NO. /	
1301 W. Grand Ave., Artesia ISM 2210	District II 1301 W. Grand Ave., Artesia CONSERVATION DIVISION District III 1220 South St. Francis Dr.		Indicate Type of	Lease
District III			STATE X	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV FEB 2	2 2010 Santa Fe, NM 875		State Oil & Gas I	
1220 S. St. Francis Dr. Santa Fe. NM		1 **	2317	Lease No.
87505 HOBB	CES AND REPORTS ON WELLS	7	Lease Name or II	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUC		Lease Maine of O	int Agreement Name
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		State 35 Unit	
PROPOSALS)			8. Well Number	
1. Type of Well:		37		/
Oil Well Gas Well Oth	ner X (WIW)	1 3 7	•	
2. Name of Operator	1	9.	OGRID Number	./
McGowan Working Partners, Inc.	J		0397	₩
3. Address of Operator			. Pool name or W	ildcat
P.O. Box 55809, Jackson MS 3929	6-5809	•	acuum – Greyburg	ν I
4. Well Location	0 3007		actually Greyoung	, Sail Tindi 65
4. Well Location				
Unit Letter P :	10 feet from the South	line and1210	feet from the	East line
Section 35	Township 17S	Range 34E	NMPM	County Lea
	11. Elevation (Show whether DR, I		5.12° A. A.	
	4010' (			
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)				
Pit Location: UL P Sect 35 Twp	17 Rng 34 Pit type lined 12 mil Deptl	to Groundwater 160	Distance from neares	t fresh water well >1000'
i .	000' Below-grade Tank Location UL			
		Sect1wp	,	
feet from theline and _	feet from theline			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK		REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	NG OPRS	LUGAND RANDONMENT/
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	DOGGAAC	disk
OTHER:		OTHER:		72-23-10
	erations. (Clearly state all pertinent details, ar	4	iding estimated date of	starting any proposed work)
	ompletions: Attach wellbore diagram of propo			starting any proposed work).
1. Pull injection tubing & packer, inspect both 13-3/8' & 5-1/2' casing. 3. Welded 4. Perform witnessed MIT & return to so	at tubing & test casing. 2. Found pinhole I on new casings and cemented in place. 4 ervice.	eak in top 5' of 5-1/2" ca . Run injection tubing &	asing, dug cellar out packer, EOT @ 430	and cut off top 11' 4" of 00' & PKR @ 4300' & test.
Note: Perfs @ 4367' – 4710'				
I hereby certify that the information	-1	t of my knowledge an	d belief. I further c	:-: <del>k</del>
Si aut tank nuo beem ii ni be combii aciea oi	closed according to NMOCD guidelines, a g			
	closed according to NMOCD guidelines, a g	general permit or an (atta	ched) alternative OCI	O-approved plan.
SIGNATURE SIGNATURE		general permit or an (atta	ched) alternative OCI	
	closed according to NMOCD guidelines, a g	general permit or an (atta  E Regulatory Off	ched) alternative OCI	O-approved plan.
SIGNATURE SIGNATURE	closed according to NMOCD guidelines, a g	general permit or an (atta  E Regulatory Off	ched) alternative OCI	D-approved planDATE_ <u>17 Feb 10</u>
Type or print name Glenn Hepne  (This space for State use)	TITL  r E-mail address: glenn(	general permit or an (atta  E Regulatory Off	ched) alternative OCI icer Telephone No.	D-approved plan. DATE_ <u>17 Feb 10</u>
SIGNATURE  Type or print name Glenn Hepne	closed according to NMOCD guidelines, a g	general permit or an (atta  E Regulatory Off	ched) alternative OCI icer Telephone No.	D-approved planDATE_ <u>17 Feb 10</u>

