Form 3160-5 (November 1994)	UNITED STATE		HERACHOLINE OF	FORM APPROVED
(November 1994)	JREAU OF LAND MAN		.4 .6 .5	OMB No. 1004-0135 Expires July 31, 1996
OCD Hobbs	1		OCD HUBBY	5. Lease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			s on Most	NM-0175774 1D3234
SUNDRY NOTICES AND REPORTS ON WELLS NM-0175774 10-3-2-3-4 Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				
7. If Unit or CA/Agreement, Name and/or No				
1 Tupo of Moll				Lusk West Delaware Unit
Oil Well Gas Well Other		FEB 1	7 2010	8. Well Name and No.
2 Name of Operator Cimarex Energy Co. of Colorado		NMOCD .	ARTESIA	Lusk West Delaware Unit No. 112
3a Address	Phone No (includ	de area code)	9. API Well No 30-025-30694 ✓ ✓	
600 N. Marienfeld St., Ste. 600; Mi	132-571-7800		10 Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., P., M., or Survey Description)				Lusk; Delaware, West
2310 FSL & 330 FWL / 21-19S-32E			11 County or Parish, State Lea County, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DA				
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent	ent Acidize Deepen Production (Start/Resume) Water Shut-Off			
_	Alter Casing F	racture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
	Change Plans	Plug and Abandon	Temporarily Aband	don
Final Abandonment Notice Convert to Injection Plug Back Water Disposal				
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 01.25.10 NDWH & NUBOP. 01.27.10 POOH w/ tbg. Could not get below 6400 with gauge ring/junk basket. Received BLM permission to change CIBP setting depth. Set CIBP @ 6390. Loaded casing with 60 bbls 2% KCl fluid. Pressured up to 500 psi for 30 minutes and held. Witnessed by Pat McKelvey of BLM. Cherry Canyon RC Plans RIH w/ tbg open-ended. ND BOP and NUWH. Pending LWDU 15 test perforate Cherry Canyon using 3 1/8" casing guns from 4718'-5006' RIH with packer and RBP. Acidize in 3 stages using 2500 gal 10% NEFE acid. Move RBP below all new perfs. Swab test to determine oil cut and fluid entry. If test successful fracture stimulation and rod pump installation under separate AFE. If not productive NOI to PA will be submitted. Request 6 month TA to test and evaluate LWDU # 15 and obtain partner approval and schedule PA rig if a no go. APPROVED FORMONTH PERIOD				
ENDING 7/27/2010				
14. I hereby certify that the foregoing is true an	d correct	1		
Name (<i>Printed/Typed</i>)		Title		
Zeno Farris			erations Administrati	ion
Signature Zano F	any	Date	040	ACCEPTED FOR RECORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by C FIELD REPRESENTATIVE MANY (-(C) Z-23-10 Title FEB. 9 2010				
Conditions of Approval, if any, are attached		Office	Isl Chris Walls	
certify that the applicant holds legal or equitable			BUREAU OF LAND MANAGEMENT	
which would entitle the applicant to conduct operations thereon. BURLAU OF LAND MANAGEMENT CARLESAND FIELD OFFILED Title 18 U.S C Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fichildross or				
fraudulent statements or representations as to any matter within its jurisdiction.				

