

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-36493
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name AFT
8. Well Number #1-Y
9. OGRID Number 021355
10. Pool name or Wildcat CAPROCK, EAST DEVONIAN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other DRY

2. Name of Operator
SOUTHWEST ROYALTIES, INC.

3. Address of Operator
P.O. BOX 11390, MIDLAND, TEXAS 79702

4. Well Location
Unit Letter C : 760 feet from the NORTH line and 1935' feet from the WEST line
Section 26 Township 12-S Range 32-E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4327' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: PLUG BACK ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


Well: AFT #1-Y API #30-025-36493 Plug and Abandonment Intent

Plugging procedure verbally approved by Mr. Gary Wink.

- Spot 100' plug on bottom.
- Straddle top of Atoka (10,076') with a 100' plug.
- Straddle top of Abo (7745') with a 100' plug.
- Straddle top of Clearfork (5620') with a 100' plug.
- Spot a 100' plug across the 8-5/8" casing shoe. WOC & tag.

50' BELOW + 50' ABOVE TAG 50' UP IN 8 5/8"

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dawn M. Howard TITLE OPERATIONS ASSISTANT DATE 1/26/04

Type or print name DAWN M. HOWARD E-mail address: dhoward@swrinc.com Telephone No. 686-9927

(This space for State use)

APPROVED BY Gary W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE JAN 28 2004