

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

OXY USA Inc.

16696

3a. Address

P.O. Box 50250 Midland, TX 79710

3b. Phone No. (include area code)

432-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FNL 1980 FEL SWNE(G) Sec 3 T24S R34E

5. Lease Serial No.

NM0327106

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Antelope Ridge Ut #6

9. API Well No.

30-025-26291

10. Field and Pool, or Exploratory Area

Antelope Ridge Morrow

11. County or Parish, State

Lea NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

RECEIVED

FEB 25 2010

HOBBSDO

See Attached

Accepted as to plugging of the well bore.  
Liability under bond is retained until  
Surface restoration is completed.



14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

David Stewart

Title

Sr. Regulatory Analyst

Date

2/16/10

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ANTELOPE RIDGE UNIT #6

1/28/10 MIRU PU  
1/29/10 NDWH, NUBOP  
RIH W/ 6-3/4" BIT, 6 - 4-1/8" DRILL COLLARS TO 2884'  
1/30/10 RIH & TAG @ 6884', DO CIBP @ 6884', PLUG LOOSE, PUSH DOWN, CIRC CLEAN  
1/31/10 CHASE CIBP TO TOP OF LINER, CIRC HOLE  
2/1/10 CHECK PRESSURE - CSG-O - TBG-100 PSI, FLOW BACK TO TANK, NU STRIPPER, POOH.  
LD 4-1/2" DRILL COLLARS, RIH W/ 6-5/8" OD X 5-5/16 ID SHOE, BUMPER SUB, JARS & COLLARS, TONGS  
BROKE DOWN  
2/2/10 RIH & TAG @ 11774', RU SWIVEL, WASH OVER & MILL ON 7-5/8" CIBP, POOH.  
2/3/10 PU 1 JT RI & TAG UP @ 11774' ATTEMPT TO CATCH CIBP IN SHOE, POOH W/ 25 JTS  
2/4/10 RD SWIVEL, WAIT ON VACCUUM TRUCK, POOH W/ TBG  
2/5/10 CONTINUE RIH W/ TBG, TAG UP @ 11774', REC BLM APPROVAL TO PLUG FROM 11774'.  
2/6/10 RU RISING STAR CEMENTERS, CIRC W/ 200BBLs 10# MUD, M&P 30SX CL H CMT, FLUSH WITH 67BBLs  
10# MUD, PUH TO 9955', WOC  
2/8/10 RIH W/ TBG TAG @ 11324', OK'D BY JACK JOHNSON-BLM  
M&P 305SX CL H CMT @ 11324', CALC TOC @ 9883'.  
PUH TO 8804', M&P 50SX CL H CMT @ 8804', CALC TOC @ 8568'  
PUH TO 6667', M&P 50SX CL H CMT @ 6667', WOC.  
2/9/10 RU WL, RIH & TAG CMT @ 6375'. PUH & PERF @ 5197', POOH W/ WL.  
RIH W/ PKR & SET @ 4848', WO ON CEMENTERS  
2/10/10 RU CEMENTERS, EIR IN PERFS @ 5197' W/ FULL RETURNS UP 7-5/8" X 10-3/4", SQZ 85SX CL C CMT, SI  
CSG & TBG, WOC 4 HRS  
REL PKR, PUH & RESET @ 3732'. RIH W/ WL & TAG CMT @ 5025', PUH & PERF @ 3970', EIR W/ FULL  
RETURNS, SQZ 80SX CL C CMT, SI CSG & TBG, WOC.  
2/11/10 REL PKR, PUH & RESET @ 1084'. RIH W/ WL, TAG CMT @ 3813', PUH & PERF @ 1320', EIR W/ FULL  
RETURNS, SQZ 80SX CL C W/ 2.5% CACL2, WOC  
REL PKR, POOH W/ TBG & PKR, RIH W/ WL & TAG CMT @ 1190', PUH & PERF @ 850', EIR W/ FULL  
RETURNS, CIRC 370SX CL C CMT TO SURF. ND BOP, TOP OFF CSG W/ CMT, RDPU, WELL P&A'D.