
Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office Fnergy, Minerals and Natural Resources	WELL API NO.
District I 1625 N. French Dr., Hobbs, NM RECEIVED District II OIL CONSERVATION DIVISION	30-025-23621
District III District IIII District III D	5. Indicate Type of Lease STATE FEE
District IV HOBBSOCD Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	The land and a Norman State of the Norman Stat
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Hobbs State
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD	8. Well Number 3 9. OGRID Number 161968
2. Name of Operator Auguste SWD Inc. Quid Resource Services LU	<i>V</i>
3. Address of Operator (Clothesquite SWD INC)	10. Pool name or Wildcat 660
P.O. Box 1479 Carlsbad NM 88221-1479	Sall Allules
4. Well Location Unit Letter B : 990 feet from the North	line and1830feet from the
East line	
Section 29 Township 18S Range 38E 11. Elevation (Show whether DR, RKB, RT, GR, e	NMPM CountyLea
11. Elevation (Show whether Br, 1915), 11, 11	
10 Cl 1 4 into Pour to Indicate Notice of Notice	a Penort or Other Data
12. Check Appropriate Box to Indicate Nature of Notic	
1101102 01 111121111011	IBSEQUENT REPORT OF: DRK ☐ ALTERING CASING ☐
PERFORM REMEDIAL MONEY	PAND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMI	ENT JOB
DOWNHOLE COMMINGLE	, 0;
ET ANUED	
OTHER: MIT OTHER:	MIT
13 Describe proposed or completed operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W Spud Date: Rig Release Date:	itness by SIvia Dickey OCD Hobbs.
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge.	itness by SIvia Dickey OCD Hobbs.
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge.	itness by SIvia Dickey OCD Hobbs.
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge. SIGNATURE May TITLE President Date:	itness by SIvia Dickey OCD Hobbs. edge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge of the second of th	itness by SIvia Dickey OCD Hobbs. edge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge or print name _Clay LWilson E-mail address:claylwilson@pccnm.com For State Use Only	itness by SIvia Dickey OCD Hobbs. edge and belief. ATE 2-25-2010 PHONE: 575-706-1840
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. Per OCD Santa fe request Mesquite ran a MIT pressured up to 535# for 30 min held. W Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge of the second of th	itness by SIvia Dickey OCD Hobbs. edge and belief.



RECEIVED

MAK 02 Zum

Heorge Barchau Uly Huk