Submit 3 Copies To Appropriate District Office State	of New Mexico	Form C-103
Position M.C. and L. Material Decreases		May 27, 2004
District I 1625 N. French Dr., Hobbs, NM-88240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III MAR 1 7 (2000) 1220 South St. Francis Dr		WELL API NO.
District II 1301 W Grand Ave Artesia NM 88210 OIL CONSERVATION DIVISION		30-025-25525
District III MAR 1 1 7000 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Aztec, NM 87410 ' La NM 97505		6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa FE, NOBBSOCD 87505	,	o. State on & das Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name G.P. Sims
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number #2
2. Name of Operator		9. OGRID Number .
Key Energy Services		9. OGRID Number 9797 \/
3. Address of Operator 6 Desta Drive Suite 4400 Midland, Tx. 79705		10. Pool name or Wildcat
4. Well Location		BSW; Salado
Unit Letter A :420 feet from the North line and 210 feet from the East line		
Section 32 Townsl	nip 21-S Range 37-	-E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐		
OTHER:	□ OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
2-2-09- Notify Buddy Hill NMOCD of Rig Up. 2-3-09 Set 7" CIBP @ 1154'. Circulate Hole With Plug Mud. Spot 25 Sx Class C1154'-1000'.		
2-4-09 Tag Plug @ 1020'. Notify Mark Whitaker NMOCD of Tag. OK to continue P & A. Spot 100 sx Class C 527'- Surface. POH		
Top Off.		
Approved for plugging of well bore only.		
Liability under bond is retained pending receipt		
of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under		
Forms, www.cmnrd.state.nm.us/ocd.		
I hereby certify that the information above is true and com		
grade tank has been/will be constructed or closed according to NMC	PCD guidelines \square , a general permit \square	or an (attached) alternative OCD-approved plan .
SIGNATURE MECHEN	TITLE P & A Supervisor	DATE2-16-10
Type or print name	E-mail address:	Telephone No.
For State Use Only OISTRICT 1 SUPERVISOR MAR 1 2 2010		
APPROVED BY: DATE DATE		
Conditions of Approval (if any)		