| Submit 3 Copies To Appro | opriate District | State of New Mexico | | | Form | 1 C-103 |
|--|---|--|---------------------------------|--|------------------------------------|-----------------------|
| Office District I | Energy, | , Minerals and Natural Res | ources | | Jun | e 19, 2008 |
| 1625 N. French Dr., Hobb | s, NM 822ECENED | A CONTRACTOR OF THE CONTRACTOR | | WELL API NO. | | \mathcal{L} |
| District II | OIL C | ONSERVATION DIVIS | SION | | 0-025-08606 | ν |
| District III | SIA, NIM 8 PAR 12 2010 11 | ONSERVATION DIVIS 220 South St. Francis Dr | | 5. Indicate Type of STATE X | Lease FEE | |
| 1000 Rio Diazos Ra., Aza | CC, NM 87410 HUBBSOCD | Santa Fe, NM 87505 | - | 6. State Oil & Gas I | | |
| District IV 1220 S. St. Francis Dr., Sa | | Suitu I e, I ii. I o , e o o | | | 5425191 | |
| 87505 | , , | DODES ON WELLS | | | | Name |
| | NDRY NOTICES AND RE | EPORTS ON WELLS . OR TO DEEPEN OR PLUG BACK | . TO 4 | 7. Lease Name or U CONE JALMAT Y. | | |
| | | RMIT" (FORM C-101) FOR SUCH | | CONE JALMAT T | ATES FOOL | ONLY |
| PROPOSALS.) | 1 Well Cos Well v | Other Water Injection Well | | 8. Well Number | 105 | |
| 1. Type of Well: Oil 2. Name of Operator | | Other water injection wen | | 9. OGRID Number | | |
| 2. Name of Operator | MELROSE OPERATING | G CO | | , | 184860 | |
| 3. Address of Operat | | | | 10. Pool name or W | | - |
| 1000 W. WILSHIRE, SUITE 223, OKLAHOMA CITY, OK 73116 | | | | Jalmat, Yates, Tans | ell,7-Rives | |
| 4. Well Location | | | | , | | |
| Unit Letter_ | L:1980fe | eet from the _SOUTH_ line | e and660 | | | line / |
| Section | | vnship 22S Range | 35E | NMPM | County LEA | |
| Part Mark | 温 : 本意に 11. Elevatio | on (Show whether DR, RKB, I | RT, GR, etc.) | | | |
| | | 3596' GL | | | | |
| | | D . T . T . M M | CNI / T | 0.1 O.1 D | 4_ | |
|] | 12. Check Appropriate | Box to Indicate Nature of | of Notice, I | Report or Other D | ata | |
| NOT | ICE OF INTENTION | TO. | SUBS | SEQUENT REPO | ORT OF: | |
| PERFORM REMEDIA | | | DIAL WORK | <u> </u> | LTERING CAS | SING 🗌 |
| TEMPORARILY ABA | | | MENCE DRIL | LING OPNS. P | AND A | |
| PULL OR ALTER CA | | | NG/CEMENT | | | |
| DOWNHOLE COMM | | | | _ | | |
| | | | | | | |
| | | | | | | |
| OTHER: | | OTHE | | CTION MIT | including activ | X mated date |
| 13. Describe pro | posed or completed operatio | ns. (Clearly state all pertinen | t details, and | give pertinent dates, | including esti | mated date |
| 13. Describe proj of starting an | y proposed work). SEE RU | | t details, and | give pertinent dates, | including estinated of proposed of | mated date |
| 13. Describe pro | y proposed work). SEE RU | ns. (Clearly state all pertinen | t details, and | give pertinent dates, | including esti of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp 50#s for 30 min, Witnessed I | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proposed of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram | of proposed o | mated date |
| 13. Describe proj of starting an or recompleti | y proposed work). SEE RU ion. | ns. (Clearly state all pertinen LE 1103. For Multiple Comp 50#s for 30 min, Witnessed I | t details, and pletions: Att | give pertinent dates, ach wellbore diagram n Harrison, SEE att | n of proposed o | mated date |
| 13. Describe proj of starting an or recompleti Performed Spud Date: | y proposed work). SEE RUion. Injection MIT, 5/12/09, 65 | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram n Harrison, SEE att | of proposed o | mated date |
| 13. Describe proj of starting an or recompleti Performed Spud Date: | y proposed work). SEE RUion. Injection MIT, 5/12/09, 65 | ns. (Clearly state all pertinen LE 1103. For Multiple Comp 50#s for 30 min, Witnessed I | t details, and pletions: Att | give pertinent dates, ach wellbore diagram n Harrison, SEE att | n of proposed o | mated date |
| 13. Describe proj of starting an or recompleti Performed Spud Date: | y proposed work). SEE RUion. Injection MIT, 5/12/09, 65 | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram n Harrison, SEE att | n of proposed o | mated date |
| 13. Describe proj of starting an or recompleti Performed Spud Date: | y proposed work). SEE RUion. Injection MIT, 5/12/09, 65 | ns. (Clearly state all pertinen LE 1103. For Multiple Comp | t details, and pletions: Att | give pertinent dates, ach wellbore diagram n Harrison, SEE att and belief. | n of proposed o | mated date |
| 13. Describe proj of starting an or recompletis Performed Spud Date: I hereby certify that the SIGNATURE | y proposed work). SEE RU ion. Injection MIT, 5/12/09, 65 ne information above is true | Rig Release Date: TITLE_Forman | t details, and pletions: Att | give pertinent dates, ach wellbore diagram n Harrison, SEE att and belief. | ached Chart 2495 E_5/12/09 | mated date completion |
| 13. Describe proj of starting an or recompletis Performed Spud Date: I hereby certify that the SIGNATURE Type or print name | y proposed work). SEE RU ion. Injection MIT, 5/12/09, 65 ne information above is true | Rig Release Date: | t details, and pletions: Att | give pertinent dates, ach wellbore diagram n Harrison, SEE att and belief. | ached Chart | mated date completion |
| 13. Describe proj of starting an or recompletis Performed Spud Date: I hereby certify that the SIGNATURE | y proposed work). SEE RU ion. Injection MIT, 5/12/09, 65 ne information above is true | Rig Release Date: TITLE_Forman | t details, and pletions: Att | pive pertinent dates, ach wellbore diagram n Harrison, SEE att and belief. DATE t.co PHONE | E_5/12/09 E:_575-390-46 | mated date completion |
| 13. Describe proj of starting an or recompletis Performed Spud Date: I hereby certify that the SIGNATURE Type or print name | y proposed work). SEE RU ion. Injection MIT, 5/12/09, 65 ne information above is true | Rig Release Date: TITLE_Forman | t details, and pletions: Att | pive pertinent dates, ach wellbore diagram n Harrison, SEE att and belief. DATE t.co PHONE | ached Chart 2495 E_5/12/09 | mated date completion |
| 13. Describe proj of starting an or recompleti Performed Spud Date: I hereby certify that the SIGNATURE Type or print name For State Use Only | y proposed work). SEE RU ion. Injection MIT, 5/12/09, 65 The information above is true Cam Robbins | Rig Release Date: TITLE_Forman E-mail address:maximus | t details, and pletions: Att | pive pertinent dates, ach wellbore diagram n Harrison, SEE att and belief. DATE t.co PHONE | E_5/12/09 E:_575-390-46 | mated date completion |

